

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
35' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2007 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2006 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 2416 | 1740 | 49.70 | 1341.92 | 670.96 | 447.31 | 335.48 | 268.38 | 223.65 |
| 2003 | 1927 | 1310 | 37.44 | 1010.85 | 505.42 | 336.95 | 252.71 | 202.17 | 168.47 |
| 2002 | 1927 | 1233 | 35.24 | 951.39 | 475.69 | 317.13 | 237.85 | 190.28 | 158.56 |
| 2001 | 1448 | 869 | 24.82 | 670.22 | 335.11 | 223.41 | 167.55 | 134.04 | 111.70 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 27 feet of Common Area per Section 16 of the *Routine Handbook*.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
40' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 7848 | 6906 | 172.66 | 5179.68 | 2589.84 | 1726.56 | 1294.92 | 1035.94 | 863.28 |
| 2007 | 6885 | 5783 | 144.59 | 4337.55 | 2168.78 | 1445.85 | 1084.39 | 867.51 | 722.93 |
| 2006 | 6494 | 5195 | 129.88 | 3896.40 | 1948.20 | 1298.80 | 974.10 | 779.28 | 649.40 |
| 2005 | 5967 | 4535 | 113.37 | 3401.19 | 1700.60 | 1133.73 | 850.30 | 680.24 | 566.87 |
| 2004 | 3201 | 2305 | 57.62 | 1728.54 | 864.27 | 576.18 | 432.14 | 345.71 | 288.09 |
| 2003 | 2603 | 1770 | 44.25 | 1327.53 | 663.77 | 442.51 | 331.88 | 265.51 | 221.26 |
| 2002 | 2603 | 1666 | 41.65 | 1249.44 | 624.72 | 416.48 | 312.36 | 249.89 | 208.24 |
| 2001 | 1794 | 1076 | 26.91 | 807.30 | 403.65 | 269.10 | 201.83 | 161.46 | 134.55 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 30 feet of Common Area per Section 16 of the *Routine Handbook*.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
45' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8072 | 7103 | 157.85 | 4735.57 | 2367.79 | 1578.52 | 1183.89 | 947.11 | 789.26 |
| 2007 | 7101 | 5965 | 132.55 | 3976.56 | 1988.28 | 1325.52 | 994.14 | 795.31 | 662.76 |
| 2006 | 6783 | 5426 | 120.59 | 3617.60 | 1808.80 | 1205.87 | 904.40 | 723.52 | 602.93 |
| 2005 | 6191 | 4705 | 104.56 | 3136.77 | 1568.39 | 1045.59 | 784.19 | 627.35 | 522.80 |
| 2004 | 3314 | 2386 | 53.02 | 1590.72 | 795.36 | 530.24 | 397.68 | 318.14 | 265.12 |
| 2003 | 2703 | 1838 | 40.85 | 1225.36 | 612.68 | 408.45 | 306.34 | 245.07 | 204.23 |
| 2002 | 2703 | 1730 | 38.44 | 1153.28 | 576.64 | 384.43 | 288.32 | 230.66 | 192.21 |
| 2001 | 1834 | 1100 | 24.45 | 733.60 | 366.80 | 244.53 | 183.40 | 146.72 | 122.27 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 30 feet of Common Area per Section 16 of the *Routine Handbook*.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
50' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 7547 | 6641 | 132.83 | 4117.64 | 2058.82 | 1372.55 | 1029.41 | 823.53 | 686.27 |
| 2007 | 6622 | 5562 | 111.25 | 3448.74 | 1724.37 | 1149.58 | 862.18 | 689.75 | 574.79 |
| 2006 | 6267 | 5014 | 100.27 | 3108.43 | 1554.22 | 1036.14 | 777.11 | 621.69 | 518.07 |
| 2005 | 5677 | 4315 | 86.29 | 2675.00 | 1337.50 | 891.67 | 668.75 | 535.00 | 445.83 |
| 2004 | 3450 | 2484 | 49.68 | 1540.08 | 770.04 | 513.36 | 385.02 | 308.02 | 256.68 |
| 2003 | 4557 | 3099 | 61.98 | 1921.23 | 960.62 | 640.41 | 480.31 | 384.25 | 320.21 |
| 2002 | 4557 | 2916 | 58.33 | 1808.22 | 904.11 | 602.74 | 452.05 | 361.64 | 301.37 |
| 2001 | 3689 | 2213 | 44.27 | 1372.31 | 686.15 | 457.44 | 343.08 | 274.46 | 228.72 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 31 feet of Common Area per Section 16 of the *Routine Handbook*.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
55' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8364 | 7360 | 133.82 | 4148.54 | 2074.27 | 1382.85 | 1037.14 | 829.71 | 691.42 |
| 2007 | 7325 | 6153 | 111.87 | 3468.05 | 1734.03 | 1156.02 | 867.01 | 693.61 | 578.01 |
| 2006 | 6879 | 5503 | 100.06 | 3101.80 | 1550.90 | 1033.93 | 775.45 | 620.36 | 516.97 |
| 2005 | 6694 | 5087 | 92.50 | 2867.47 | 1433.73 | 955.82 | 716.87 | 573.49 | 477.91 |
| 2004 | 5869 | 4226 | 76.83 | 2381.75 | 1190.87 | 793.92 | 595.44 | 476.35 | 396.96 |
| 2003 | 5383 | 3660 | 66.55 | 2063.16 | 1031.58 | 687.72 | 515.79 | 412.63 | 343.86 |
| 2002 | 5383 | 3445 | 62.64 | 1941.79 | 970.90 | 647.26 | 485.45 | 388.36 | 323.63 |
| 2001 | 4514 | 2708 | 49.24 | 1526.55 | 763.28 | 508.85 | 381.64 | 305.31 | 254.43 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 31 feet of Common Area per Section 16 of the *Routine Handbook*.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
60' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8856 | 7793 | 129.89 | 4156.42 | 2078.21 | 1385.47 | 1039.10 | 831.28 | 692.74 |
| 2007 | 7772 | 6528 | 108.81 | 3481.86 | 1740.93 | 1160.62 | 870.46 | 696.37 | 580.31 |
| 2006 | 7740 | 6192 | 103.20 | 3302.40 | 1651.20 | 1100.80 | 825.60 | 660.48 | 550.40 |
| 2005 | 7559 | 5745 | 95.75 | 3063.91 | 1531.96 | 1021.30 | 765.98 | 612.78 | 510.65 |
| 2004 | 5943 | 4279 | 71.32 | 2282.11 | 1141.06 | 760.70 | 570.53 | 456.42 | 380.35 |
| 2003 | 5977 | 4064 | 67.74 | 2167.66 | 1083.83 | 722.55 | 541.91 | 433.53 | 361.28 |
| 2002 | 5977 | 3825 | 63.75 | 2040.15 | 1020.07 | 680.05 | 510.04 | 408.03 | 340.02 |
| 2001 | 5048 | 3029 | 50.48 | 1615.36 | 807.68 | 538.45 | 403.84 | 323.07 | 269.23 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
65' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 9824 | 8645 | 133.00 | 4256.06 | 2128.03 | 1418.69 | 1064.01 | 851.21 | 709.34 |
| 2007 | 8630 | 7249 | 111.53 | 3568.84 | 1784.42 | 1189.61 | 892.21 | 713.77 | 594.81 |
| 2006 | 8376 | 6701 | 103.09 | 3298.86 | 1649.43 | 1099.62 | 824.71 | 659.77 | 549.81 |
| 2005 | 8166 | 6206 | 95.48 | 3055.34 | 1527.67 | 1018.45 | 763.84 | 611.07 | 509.22 |
| 2004 | 6432 | 4631 | 71.25 | 2279.90 | 1139.95 | 759.97 | 569.97 | 455.98 | 379.98 |
| 2003 | 6448 | 4385 | 67.46 | 2158.59 | 1079.30 | 719.53 | 539.65 | 431.72 | 359.77 |
| 2002 | 6448 | 4127 | 63.49 | 2031.62 | 1015.81 | 677.21 | 507.90 | 406.32 | 338.60 |
| 2001 | 5520 | 3312 | 50.95 | 1630.52 | 815.26 | 543.51 | 407.63 | 326.10 | 271.75 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
70' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 10809 | 9512 | 135.88 | 4484.19 | 2242.10 | 1494.73 | 1121.05 | 896.84 | 747.37 |
| 2007 | 9931 | 8342 | 119.17 | 3932.68 | 1966.34 | 1310.89 | 983.17 | 786.54 | 655.45 |
| 2006 | 8911 | 7129 | 101.84 | 3360.72 | 1680.36 | 1120.24 | 840.18 | 672.14 | 560.12 |
| 2005 | 8704 | 6615 | 94.50 | 3118.52 | 1559.26 | 1039.51 | 779.63 | 623.70 | 519.75 |
| 2004 | 6771 | 4875 | 69.64 | 2298.27 | 1149.14 | 766.09 | 574.57 | 459.65 | 383.05 |
| 2003 | 6833 | 4646 | 66.38 | 2190.46 | 1095.23 | 730.15 | 547.62 | 438.09 | 365.08 |
| 2002 | 6833 | 4373 | 62.47 | 2061.61 | 1030.81 | 687.20 | 515.40 | 412.32 | 343.60 |
| 2001 | 5904 | 3542 | 50.61 | 1669.99 | 834.99 | 556.66 | 417.50 | 334.00 | 278.33 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
75' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 11590 | 10199 | 135.99 | 4487.65 | 2243.82 | 1495.88 | 1121.91 | 897.53 | 747.94 |
| 2007 | 10600 | 8904 | 118.72 | 3917.76 | 1958.88 | 1305.92 | 979.44 | 783.55 | 652.96 |
| 2006 | 9512 | 7610 | 101.46 | 3348.22 | 1674.11 | 1116.07 | 837.06 | 669.64 | 558.04 |
| 2005 | 9308 | 7074 | 94.32 | 3112.60 | 1556.30 | 1037.53 | 778.15 | 622.52 | 518.77 |
| 2004 | 7153 | 5150 | 68.67 | 2266.07 | 1133.04 | 755.36 | 566.52 | 453.21 | 377.68 |
| 2003 | 7171 | 4876 | 65.02 | 2145.56 | 1072.78 | 715.19 | 536.39 | 429.11 | 357.59 |
| 2002 | 7171 | 4589 | 61.19 | 2019.35 | 1009.68 | 673.12 | 504.84 | 403.87 | 336.56 |
| 2001 | 6242 | 3745 | 49.94 | 1647.89 | 823.94 | 549.30 | 411.97 | 329.58 | 274.65 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
80' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 11933 | 10501 | 131.26 | 4462.94 | 2231.47 | 1487.65 | 1115.74 | 892.59 | 743.82 |
| 2007 | 10913 | 9167 | 114.59 | 3895.94 | 1947.97 | 1298.65 | 973.99 | 779.19 | 649.32 |
| 2006 | 9885 | 7908 | 98.85 | 3360.90 | 1680.45 | 1120.30 | 840.23 | 672.18 | 560.15 |
| 2005 | 9680 | 7357 | 91.96 | 3126.64 | 1563.32 | 1042.21 | 781.66 | 625.33 | 521.11 |
| 2004 | 7383 | 5316 | 66.45 | 2259.20 | 1129.60 | 753.07 | 564.80 | 451.84 | 376.53 |
| 2003 | 7664 | 5212 | 65.14 | 2214.90 | 1107.45 | 738.30 | 553.72 | 442.98 | 369.15 |
| 2002 | 7664 | 4905 | 61.31 | 2084.61 | 1042.30 | 694.87 | 521.15 | 416.92 | 347.43 |
| 2001 | 6735 | 4041 | 50.51 | 1717.43 | 858.71 | 572.48 | 429.36 | 343.49 | 286.24 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
85' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 12505 | 11004 | 129.46 | 4401.76 | 2200.88 | 1467.25 | 1100.44 | 880.35 | 733.63 |
| 2007 | 11416 | 9589 | 112.82 | 3835.78 | 1917.89 | 1278.59 | 958.94 | 767.16 | 639.30 |
| 2006 | 10501 | 8401 | 98.83 | 3360.32 | 1680.16 | 1120.11 | 840.08 | 672.06 | 560.05 |
| 2005 | 10300 | 7828 | 92.09 | 3131.20 | 1565.60 | 1043.73 | 782.80 | 626.24 | 521.87 |
| 2004 | 7643 | 5503 | 64.74 | 2201.18 | 1100.59 | 733.73 | 550.30 | 440.24 | 366.86 |
| 2003 | 7627 | 5186 | 61.02 | 2074.54 | 1037.27 | 691.51 | 518.64 | 414.91 | 345.76 |
| 2002 | 7627 | 4881 | 57.43 | 1952.51 | 976.26 | 650.84 | 488.13 | 390.50 | 325.42 |
| 2001 | 6698 | 4019 | 47.28 | 1607.52 | 803.76 | 535.84 | 401.88 | 321.50 | 267.92 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
90' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 13797 | 12141 | 134.90 | 4721.64 | 2360.82 | 1573.88 | 1180.41 | 944.33 | 786.94 |
| 2007 | 12616 | 10597 | 117.75 | 4121.23 | 2060.61 | 1373.74 | 1030.31 | 824.25 | 686.87 |
| 2006 | 10848 | 8678 | 96.43 | 3374.93 | 1687.47 | 1124.98 | 843.73 | 674.99 | 562.49 |
| 2005 | 10604 | 8059 | 89.54 | 3134.07 | 1567.04 | 1044.69 | 783.52 | 626.81 | 522.35 |
| 2004 | 8259 | 5946 | 66.07 | 2312.52 | 1156.26 | 770.84 | 578.13 | 462.50 | 385.42 |
| 2003 | 8477 | 5764 | 64.05 | 2241.70 | 1120.85 | 747.23 | 560.42 | 448.34 | 373.62 |
| 2002 | 8477 | 5425 | 60.28 | 2109.83 | 1054.92 | 703.28 | 527.46 | 421.97 | 351.64 |
| 2001 | 7458 | 4475 | 49.72 | 1740.20 | 870.10 | 580.07 | 435.05 | 348.04 | 290.03 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
95' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14185 | 12483 | 131.40 | 4598.93 | 2299.46 | 1532.98 | 1149.73 | 919.79 | 766.49 |
| 2007 | 12966 | 10891 | 114.65 | 4012.64 | 2006.32 | 1337.55 | 1003.16 | 802.53 | 668.77 |
| 2006 | 11526 | 9221 | 97.06 | 3397.14 | 1698.57 | 1132.38 | 849.28 | 679.43 | 566.19 |
| 2005 | 11286 | 8577 | 90.29 | 3160.08 | 1580.04 | 1053.36 | 790.02 | 632.02 | 526.68 |
| 2004 | 8558 | 6162 | 64.86 | 2270.12 | 1135.06 | 756.71 | 567.53 | 454.02 | 378.35 |
| 2003 | 8828 | 6003 | 63.19 | 2211.65 | 1105.82 | 737.22 | 552.91 | 442.33 | 368.61 |
| 2002 | 8828 | 5650 | 59.47 | 2081.55 | 1040.77 | 693.85 | 520.39 | 416.31 | 346.92 |
| 2001 | 7810 | 4686 | 49.33 | 1726.42 | 863.21 | 575.47 | 431.61 | 345.28 | 287.74 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
100' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14324 | 12605 | 126.05 | 4411.79 | 2205.90 | 1470.60 | 1102.95 | 882.36 | 735.30 |
| 2007 | 13117 | 11018 | 110.18 | 3856.40 | 1928.20 | 1285.47 | 964.10 | 771.28 | 642.73 |
| 2006 | 12413 | 9930 | 99.30 | 3475.64 | 1737.82 | 1158.55 | 868.91 | 695.13 | 579.27 |
| 2005 | 12178 | 9255 | 92.55 | 3239.35 | 1619.67 | 1079.78 | 809.84 | 647.87 | 539.89 |
| 2004 | 8558 | 6162 | 61.62 | 2156.62 | 1078.31 | 718.87 | 539.15 | 431.32 | 359.44 |
| 2003 | 9201 | 6257 | 62.57 | 2189.84 | 1094.92 | 729.95 | 547.46 | 437.97 | 364.97 |
| 2002 | 9201 | 5889 | 58.89 | 2061.02 | 1030.51 | 687.01 | 515.26 | 412.20 | 343.50 |
| 2001 | 8183 | 4910 | 49.10 | 1718.43 | 859.22 | 572.81 | 429.61 | 343.69 | 286.41 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
105' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14639 | 12882 | 122.69 | 4294.11 | 2147.05 | 1431.37 | 1073.53 | 858.82 | 715.68 |
| 2007 | 13398 | 11254 | 107.18 | 3751.44 | 1875.72 | 1250.48 | 937.86 | 750.29 | 625.24 |
| 2006 | 13001 | 10401 | 99.06 | 3466.93 | 1733.47 | 1155.64 | 866.73 | 693.39 | 577.82 |
| 2005 | 13005 | 9884 | 94.13 | 3294.60 | 1647.30 | 1098.20 | 823.65 | 658.92 | 549.10 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2011 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
110' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2011 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 16242 | 14293 | 129.94 | 4547.76 | 2273.88 | 1515.92 | 1136.94 | 909.55 | 757.96 |
| 2007 | 14773 | 12409 | 112.81 | 3948.42 | 1974.21 | 1316.14 | 987.11 | 789.68 | 658.07 |
| 2006 | 14479 | 11583 | 105.30 | 3685.56 | 1842.78 | 1228.52 | 921.39 | 737.11 | 614.26 |
| 2005 | 14256 | 10835 | 98.50 | 3447.36 | 1723.68 | 1149.12 | 861.84 | 689.47 | 574.56 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

