

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
30' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	3977	2883	96.11	2402.77	1201.39	800.92	600.69	480.55	400.46
2007	3468	2428	80.92	2023.00	1011.50	674.33	505.75	404.60	337.17
2006	3080	2079	69.30	1732.50	866.25	577.50	433.13	346.50	288.75
2005	2836	1843	61.45	1536.17	768.08	512.06	384.04	307.23	256.03
2004	2957	1848	61.60	1540.10	770.05	513.37	385.03	308.02	256.68
2003	2767	1660	55.34	1383.50	691.75	461.17	345.88	276.70	230.58
2002	2767	1591	53.03	1325.85	662.93	441.95	331.46	265.17	220.98
2001	2088	1148	38.28	957.00	478.50	319.00	239.25	191.40	159.50
2000	2555	1341	44.71	1117.81	558.91	372.60	279.45	223.56	186.30
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 25 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
35' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4132	2996	85.59	2482.15	1241.08	827.38	620.54	496.43	413.69
2007	3591	2514	71.82	2082.78	1041.39	694.26	520.70	416.56	347.13
2006	3194	2156	61.60	1786.36	893.18	595.45	446.59	357.27	297.73
2005	2797	1818	51.94	1506.38	753.19	502.13	376.60	301.28	251.06
2004	2996	1873	53.50	1551.50	775.75	517.17	387.88	310.30	258.58
2003	2804	1682	48.07	1393.99	696.99	464.66	348.50	278.80	232.33
2002	2804	1612	46.07	1335.91	667.95	445.30	333.98	267.18	222.65
2001	2094	1152	32.91	954.27	477.13	318.09	238.57	190.85	159.04
2000	2583	1356	38.75	1123.61	561.80	374.54	280.90	224.72	187.27
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 29 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
40' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4728	3428	85.70	2570.85	1285.43	856.95	642.71	514.17	428.48
2007	4308	3016	75.39	2261.70	1130.85	753.90	565.43	452.34	376.95
2006	3836	2589	64.73	1941.98	970.99	647.33	485.49	388.40	323.66
2005	3260	2119	52.98	1589.25	794.63	529.75	397.31	317.85	264.88
2004	3482	2176	54.41	1632.19	816.09	544.06	408.05	326.44	272.03
2003	3271	1963	49.07	1471.95	735.98	490.65	367.99	294.39	245.33
2002	3271	1881	47.02	1410.62	705.31	470.21	352.65	282.12	235.10
2001	2566	1411	35.28	1058.48	529.24	352.83	264.62	211.70	176.41
2000	3141	1649	41.23	1236.77	618.38	412.26	309.19	247.35	206.13
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
45' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5031	3647	81.06	2431.65	1215.83	810.55	607.91	486.33	405.28
2007	4587	3211	71.35	2140.60	1070.30	713.53	535.15	428.12	356.77
2006	4087	2759	61.31	1839.15	919.58	613.05	459.79	367.83	306.53
2005	3299	2144	47.65	1429.57	714.78	476.52	357.39	285.91	238.26
2004	3628	2268	50.39	1511.67	755.83	503.89	377.92	302.33	251.94
2003	3429	2057	45.72	1371.60	685.80	457.20	342.90	274.32	228.60
2002	3429	1972	43.82	1314.45	657.23	438.15	328.61	262.89	219.08
2001	2696	1483	32.95	988.53	494.27	329.51	247.13	197.71	164.76
2000	3284	1724	38.31	1149.40	574.70	383.13	287.35	229.88	191.57
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
50' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5614	4070	81.40	2523.49	1261.75	841.16	630.87	504.70	420.58
2007	5125	3588	71.75	2224.25	1112.13	741.42	556.06	444.85	370.71
2006	4592	3100	61.99	1921.75	960.88	640.58	480.44	384.35	320.29
2005	3722	2419	48.39	1499.97	749.98	499.99	374.99	299.99	249.99
2004	3742	2339	46.78	1450.03	725.01	483.34	362.51	290.01	241.67
2003	4196	2518	50.35	1560.91	780.46	520.30	390.23	312.18	260.15
2002	4196	2413	48.25	1495.87	747.94	498.62	373.97	299.17	249.31
2001	3386	1862	37.25	1154.63	577.31	384.88	288.66	230.93	192.44
2000	4171	2190	43.80	1357.66	678.83	452.55	339.42	271.53	226.28
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
55' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	6586	4775	86.82	2691.28	1345.64	897.09	672.82	538.26	448.55
2007	6042	4229	76.90	2383.84	1191.92	794.61	595.96	476.77	397.31
2006	5180	3497	63.57	1970.75	985.38	656.92	492.69	394.15	328.46
2005	4496	2922	53.13	1647.17	823.59	549.06	411.79	329.43	274.53
2004	4507	2817	51.22	1587.69	793.85	529.23	396.92	317.54	264.62
2003	5643	3386	61.56	1908.36	954.18	636.12	477.09	381.67	318.06
2002	5643	3245	59.00	1828.85	914.42	609.62	457.21	365.77	304.81
2001	4721	2597	47.21	1463.51	731.76	487.84	365.88	292.70	243.92
2000	5480	2877	52.31	1621.58	810.79	540.53	405.40	324.32	270.26
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
60' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	9333	6766	112.77	3608.76	1804.38	1202.92	902.19	721.75	601.46
2007	8639	6047	100.79	3225.23	1612.61	1075.08	806.31	645.05	537.54
2006	6211	4192	69.87	2235.96	1117.98	745.32	558.99	447.19	372.66
2005	5084	3305	55.08	1762.45	881.23	587.48	440.61	352.49	293.74
2004	5103	3189	53.16	1701.00	850.50	567.00	425.25	340.20	283.50
2003	6135	3681	61.35	1963.20	981.60	654.40	490.80	392.64	327.20
2002	6135	3528	58.79	1881.40	940.70	627.13	470.35	376.28	313.57
2001	4924	2708	45.14	1444.37	722.19	481.46	361.09	288.87	240.73
2000	6141	3224	53.73	1719.48	859.74	573.16	429.87	343.90	286.58
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
65' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	10533	7636	117.48	3759.47	1879.74	1253.16	939.87	751.89	626.58
2007	10089	7062	108.65	3476.82	1738.41	1158.94	869.21	695.36	579.47
2006	9604	6483	99.73	3191.48	1595.74	1063.83	797.87	638.30	531.91
2005	6381	4148	63.81	2041.92	1020.96	680.64	510.48	408.38	340.32
2004	6410	4006	61.63	1972.31	986.15	657.44	493.08	394.46	328.72
2003	6950	4170	64.15	2052.92	1026.46	684.31	513.23	410.58	342.15
2002	6950	3996	61.48	1967.38	983.69	655.79	491.85	393.48	327.90
2001	5618	3090	47.54	1521.18	760.59	507.06	380.30	304.24	253.53
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
70' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	11167	8096	115.66	3816.72	1908.36	1272.24	954.18	763.34	636.12
2007	11047	7733	110.47	3645.51	1822.76	1215.17	911.38	729.10	607.59
2006	9604	6483	92.61	3056.13	1528.07	1018.71	764.03	611.23	509.36
2005	6574	4273	61.04	2014.46	1007.23	671.49	503.62	402.89	335.74
2004	6606	4129	58.98	1946.41	973.21	648.80	486.60	389.28	324.40
2003	7368	4421	63.15	2084.09	1042.05	694.70	521.02	416.82	347.35
2002	7368	4237	60.52	1997.25	998.63	665.75	499.31	399.45	332.88
2001	5945	3270	46.71	1541.45	770.73	513.82	385.36	308.29	256.91
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
30' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	1092	792	26.39	659.75	329.88	219.92	164.94	131.95	109.96
2007	942	659	21.98	549.50	274.75	183.17	137.38	109.90	91.58
2006	920	621	20.70	517.50	258.75	172.50	129.38	103.50	86.25
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 25 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
35' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	1212	879	25.11	728.07	364.03	242.69	182.02	145.61	121.34
2007	1039	727	20.78	602.62	301.31	200.87	150.66	120.52	100.44
2006	1018	687	19.63	569.35	284.68	189.78	142.34	113.87	94.89
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 29 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
40' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	1342	973	24.32	729.71	364.86	243.24	182.43	145.94	121.62
2007	1306	914	22.86	685.65	342.83	228.55	171.41	137.13	114.28
2006	1281	865	21.62	648.51	324.25	216.17	162.13	129.70	108.08
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
45' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	1575	1142	25.38	761.25	380.63	253.75	190.31	152.25	126.88
2007	1523	1066	23.69	710.73	355.37	236.91	177.68	142.15	118.46
2006	1494	1008	22.41	672.30	336.15	224.10	168.08	134.46	112.05
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
50' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	2025	1468	29.36	910.24	455.12	303.41	227.56	182.05	151.71
2007	1953	1367	27.34	847.60	423.80	282.53	211.90	169.52	141.27
2006	1923	1298	25.96	804.78	402.39	268.26	201.19	160.96	134.13
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
55' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	2775	2012	36.58	1133.97	566.98	377.99	283.49	226.79	188.99
2007	2679	1875	34.10	1056.99	528.49	352.33	264.25	211.40	176.16
2006	2424	1636	29.75	922.22	461.11	307.41	230.56	184.44	153.70
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
60' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4893	3547	59.12	1891.96	945.98	630.65	472.99	378.39	315.33
2007	4734	3314	55.23	1767.36	883.68	589.12	441.84	353.47	294.56
2006	3301	2228	37.14	1188.36	594.18	396.12	297.09	237.67	198.06
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
65' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5490	3980	61.23	1959.51	979.75	653.17	489.88	391.90	326.58
2007	5581	3907	60.10	1923.30	961.65	641.10	480.82	384.66	320.55
2006	5904	3985	61.31	1961.94	980.97	653.98	490.49	392.39	326.99
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
70' COMPOSITE FIBERGLASS POLE**

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5495	3984	56.91	1878.11	939.06	626.04	469.53	375.62	313.02
2007	5581	3907	55.81	1841.73	920.87	613.91	460.43	368.35	306.96
2006	5904	3985	56.93	1878.74	939.37	626.25	469.68	375.75	313.12
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.