

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
35' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2007 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2006 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 2416 | 1546 | 44.18 | 1281.17 | 640.59 | 427.06 | 320.29 | 256.23 | 213.53 |
| 2003 | 1927 | 1156 | 33.03 | 957.99 | 479.00 | 319.33 | 239.50 | 191.60 | 159.67 |
| 2002 | 1927 | 1079 | 30.83 | 894.13 | 447.06 | 298.04 | 223.53 | 178.83 | 149.02 |
| 2001 | 1448 | 753 | 21.51 | 623.88 | 311.94 | 207.96 | 155.97 | 124.78 | 103.98 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 29 feet of Common Area per Section 16 of the *Routine Handbook*.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
40' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 7848 | 6278 | 156.96 | 4708.80 | 2354.40 | 1569.60 | 1177.20 | 941.76 | 784.80 |
| 2007 | 6885 | 5233 | 130.82 | 3924.45 | 1962.23 | 1308.15 | 981.11 | 784.89 | 654.08 |
| 2006 | 6494 | 4676 | 116.89 | 3506.76 | 1753.38 | 1168.92 | 876.69 | 701.35 | 584.46 |
| 2005 | 5967 | 4058 | 101.44 | 3043.17 | 1521.59 | 1014.39 | 760.79 | 608.63 | 507.20 |
| 2004 | 3201 | 2049 | 51.22 | 1536.48 | 768.24 | 512.16 | 384.12 | 307.30 | 256.08 |
| 2003 | 2603 | 1562 | 39.05 | 1171.35 | 585.68 | 390.45 | 292.84 | 234.27 | 195.23 |
| 2002 | 2603 | 1458 | 36.44 | 1093.26 | 546.63 | 364.42 | 273.32 | 218.65 | 182.21 |
| 2001 | 1794 | 933 | 23.32 | 699.66 | 349.83 | 233.22 | 174.92 | 139.93 | 116.61 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 30 feet of Common Area per Section 16 of the *Routine Handbook*.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
45' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8072 | 6458 | 143.50 | 4305.07 | 2152.53 | 1435.02 | 1076.27 | 861.01 | 717.51 |
| 2007 | 7101 | 5397 | 119.93 | 3597.84 | 1798.92 | 1199.28 | 899.46 | 719.57 | 599.64 |
| 2006 | 6783 | 4884 | 108.53 | 3255.84 | 1627.92 | 1085.28 | 813.96 | 651.17 | 542.64 |
| 2005 | 6191 | 4210 | 93.55 | 2806.59 | 1403.29 | 935.53 | 701.65 | 561.32 | 467.76 |
| 2004 | 3314 | 2121 | 47.13 | 1413.97 | 706.99 | 471.32 | 353.49 | 282.79 | 235.66 |
| 2003 | 2703 | 1622 | 36.04 | 1081.20 | 540.60 | 360.40 | 270.30 | 216.24 | 180.20 |
| 2002 | 2703 | 1514 | 33.64 | 1009.12 | 504.56 | 336.37 | 252.28 | 201.82 | 168.19 |
| 2001 | 1834 | 954 | 21.19 | 635.79 | 317.89 | 211.93 | 158.95 | 127.16 | 105.96 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 30 feet of Common Area per Section 16 of the *Routine Handbook*.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
50' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 7547 | 6038 | 120.75 | 3743.31 | 1871.66 | 1247.77 | 935.83 | 748.66 | 623.89 |
| 2007 | 6622 | 5033 | 100.65 | 3120.29 | 1560.14 | 1040.10 | 780.07 | 624.06 | 520.05 |
| 2006 | 6267 | 4512 | 90.24 | 2797.59 | 1398.79 | 932.53 | 699.40 | 559.52 | 466.26 |
| 2005 | 5677 | 3860 | 77.21 | 2393.42 | 1196.71 | 797.81 | 598.36 | 478.68 | 398.90 |
| 2004 | 3450 | 2208 | 44.16 | 1368.96 | 684.48 | 456.32 | 342.24 | 273.79 | 228.16 |
| 2003 | 4557 | 2734 | 54.68 | 1695.20 | 847.60 | 565.07 | 423.80 | 339.04 | 282.53 |
| 2002 | 4557 | 2552 | 51.04 | 1582.19 | 791.10 | 527.40 | 395.55 | 316.44 | 263.70 |
| 2001 | 3689 | 1918 | 38.37 | 1189.33 | 594.67 | 396.44 | 297.33 | 237.87 | 198.22 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 31 feet of Common Area per Section 16 of the *Routine Handbook*.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
55' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8364 | 6691 | 121.66 | 3771.40 | 1885.70 | 1257.13 | 942.85 | 754.28 | 628.57 |
| 2007 | 7325 | 5567 | 101.22 | 3137.76 | 1568.88 | 1045.92 | 784.44 | 627.55 | 522.96 |
| 2006 | 6879 | 4953 | 90.05 | 2791.62 | 1395.81 | 930.54 | 697.91 | 558.32 | 465.27 |
| 2005 | 6694 | 4552 | 82.76 | 2565.63 | 1282.81 | 855.21 | 641.41 | 513.13 | 427.60 |
| 2004 | 5869 | 3756 | 68.29 | 2117.11 | 1058.55 | 705.70 | 529.28 | 423.42 | 352.85 |
| 2003 | 5383 | 3230 | 58.72 | 1820.43 | 910.22 | 606.81 | 455.11 | 364.09 | 303.41 |
| 2002 | 5383 | 3014 | 54.81 | 1699.07 | 849.54 | 566.36 | 424.77 | 339.81 | 283.18 |
| 2001 | 4514 | 2347 | 42.68 | 1323.01 | 661.51 | 441.00 | 330.75 | 264.60 | 220.50 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 31 feet of Common Area per Section 16 of the *Routine Handbook*.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
60' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8856 | 7085 | 118.08 | 3778.56 | 1889.28 | 1259.52 | 944.64 | 755.71 | 629.76 |
| 2007 | 7772 | 5907 | 98.45 | 3150.25 | 1575.13 | 1050.08 | 787.56 | 630.05 | 525.04 |
| 2006 | 7740 | 5573 | 92.88 | 2972.16 | 1486.08 | 990.72 | 743.04 | 594.43 | 495.36 |
| 2005 | 7559 | 5140 | 85.67 | 2741.40 | 1370.70 | 913.80 | 685.35 | 548.28 | 456.90 |
| 2004 | 5943 | 3804 | 63.39 | 2028.54 | 1014.27 | 676.18 | 507.14 | 405.71 | 338.09 |
| 2003 | 5977 | 3586 | 59.77 | 1912.64 | 956.32 | 637.55 | 478.16 | 382.53 | 318.77 |
| 2002 | 5977 | 3347 | 55.79 | 1785.13 | 892.57 | 595.04 | 446.28 | 357.03 | 297.52 |
| 2001 | 5048 | 2625 | 43.75 | 1399.98 | 699.99 | 466.66 | 349.99 | 280.00 | 233.33 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
65' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 9824 | 7859 | 120.91 | 3869.14 | 1934.57 | 1289.71 | 967.29 | 773.83 | 644.86 |
| 2007 | 8630 | 6559 | 100.90 | 3228.95 | 1614.47 | 1076.32 | 807.24 | 645.79 | 538.16 |
| 2006 | 8376 | 6031 | 92.78 | 2968.97 | 1484.48 | 989.66 | 742.24 | 593.79 | 494.83 |
| 2005 | 8166 | 5553 | 85.43 | 2733.73 | 1366.86 | 911.24 | 683.43 | 546.75 | 455.62 |
| 2004 | 6432 | 4116 | 63.33 | 2026.57 | 1013.29 | 675.52 | 506.64 | 405.31 | 337.76 |
| 2003 | 6448 | 3869 | 59.52 | 1904.64 | 952.32 | 634.88 | 476.16 | 380.93 | 317.44 |
| 2002 | 6448 | 3611 | 55.55 | 1777.66 | 888.83 | 592.55 | 444.42 | 355.53 | 296.28 |
| 2001 | 5520 | 2870 | 44.16 | 1413.12 | 706.56 | 471.04 | 353.28 | 282.62 | 235.52 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
70' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 10809 | 8647 | 123.53 | 4076.54 | 2038.27 | 1358.85 | 1019.13 | 815.31 | 679.42 |
| 2007 | 9931 | 7548 | 107.82 | 3558.14 | 1779.07 | 1186.05 | 889.53 | 711.63 | 593.02 |
| 2006 | 8911 | 6416 | 91.66 | 3024.65 | 1512.32 | 1008.22 | 756.16 | 604.93 | 504.11 |
| 2005 | 8704 | 5919 | 84.55 | 2790.25 | 1395.13 | 930.08 | 697.56 | 558.05 | 465.04 |
| 2004 | 6771 | 4333 | 61.91 | 2042.91 | 1021.45 | 680.97 | 510.73 | 408.58 | 340.48 |
| 2003 | 6833 | 4100 | 58.57 | 1932.76 | 966.38 | 644.25 | 483.19 | 386.55 | 322.13 |
| 2002 | 6833 | 3826 | 54.66 | 1803.91 | 901.96 | 601.30 | 450.98 | 360.78 | 300.65 |
| 2001 | 5904 | 3070 | 43.86 | 1447.32 | 723.66 | 482.44 | 361.83 | 289.46 | 241.22 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
75' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 11590 | 9272 | 123.63 | 4079.68 | 2039.84 | 1359.89 | 1019.92 | 815.94 | 679.95 |
| 2007 | 10600 | 8056 | 107.41 | 3544.64 | 1772.32 | 1181.55 | 886.16 | 708.93 | 590.77 |
| 2006 | 9512 | 6849 | 91.32 | 3013.40 | 1506.70 | 1004.47 | 753.35 | 602.68 | 502.23 |
| 2005 | 9308 | 6329 | 84.39 | 2784.95 | 1392.48 | 928.32 | 696.24 | 556.99 | 464.16 |
| 2004 | 7153 | 4578 | 61.04 | 2014.28 | 1007.14 | 671.43 | 503.57 | 402.86 | 335.71 |
| 2003 | 7171 | 4303 | 57.37 | 1893.14 | 946.57 | 631.05 | 473.29 | 378.63 | 315.52 |
| 2002 | 7171 | 4016 | 53.54 | 1766.93 | 883.47 | 588.98 | 441.73 | 353.39 | 294.49 |
| 2001 | 6242 | 3246 | 43.28 | 1428.17 | 714.08 | 476.06 | 357.04 | 285.63 | 238.03 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
80' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 11933 | 9546 | 119.33 | 4057.22 | 2028.61 | 1352.41 | 1014.31 | 811.44 | 676.20 |
| 2007 | 10913 | 8294 | 103.67 | 3524.90 | 1762.45 | 1174.97 | 881.22 | 704.98 | 587.48 |
| 2006 | 9885 | 7117 | 88.97 | 3024.81 | 1512.41 | 1008.27 | 756.20 | 604.96 | 504.14 |
| 2005 | 9680 | 6582 | 82.28 | 2797.52 | 1398.76 | 932.51 | 699.38 | 559.50 | 466.25 |
| 2004 | 7383 | 4725 | 59.06 | 2008.18 | 1004.09 | 669.39 | 502.04 | 401.64 | 334.70 |
| 2003 | 7664 | 4598 | 57.48 | 1954.32 | 977.16 | 651.44 | 488.58 | 390.86 | 325.72 |
| 2002 | 7664 | 4292 | 53.65 | 1824.03 | 912.02 | 608.01 | 456.01 | 364.81 | 304.01 |
| 2001 | 6735 | 3502 | 43.78 | 1488.44 | 744.22 | 496.15 | 372.11 | 297.69 | 248.07 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
85' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 12505 | 10004 | 117.69 | 4001.60 | 2000.80 | 1333.87 | 1000.40 | 800.32 | 666.93 |
| 2007 | 11416 | 8676 | 102.07 | 3470.46 | 1735.23 | 1156.82 | 867.62 | 694.09 | 578.41 |
| 2006 | 10501 | 7561 | 88.95 | 3024.29 | 1512.14 | 1008.10 | 756.07 | 604.86 | 504.05 |
| 2005 | 10300 | 7004 | 82.40 | 2801.60 | 1400.80 | 933.87 | 700.40 | 560.32 | 466.93 |
| 2004 | 7643 | 4892 | 57.55 | 1956.61 | 978.30 | 652.20 | 489.15 | 391.32 | 326.10 |
| 2003 | 7627 | 4576 | 53.84 | 1830.48 | 915.24 | 610.16 | 457.62 | 366.10 | 305.08 |
| 2002 | 7627 | 4271 | 50.25 | 1708.45 | 854.22 | 569.48 | 427.11 | 341.69 | 284.74 |
| 2001 | 6698 | 3483 | 40.98 | 1393.18 | 696.59 | 464.39 | 348.30 | 278.64 | 232.20 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
90' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 13797 | 11038 | 122.64 | 4292.40 | 2146.20 | 1430.80 | 1073.10 | 858.48 | 715.40 |
| 2007 | 12616 | 9588 | 106.54 | 3728.73 | 1864.36 | 1242.91 | 932.18 | 745.75 | 621.45 |
| 2006 | 10848 | 7811 | 86.78 | 3037.44 | 1518.72 | 1012.48 | 759.36 | 607.49 | 506.24 |
| 2005 | 10604 | 7211 | 80.12 | 2804.17 | 1402.08 | 934.72 | 701.04 | 560.83 | 467.36 |
| 2004 | 8259 | 5286 | 58.73 | 2055.57 | 1027.79 | 685.19 | 513.89 | 411.11 | 342.60 |
| 2003 | 8477 | 5086 | 56.51 | 1977.97 | 988.98 | 659.32 | 494.49 | 395.59 | 329.66 |
| 2002 | 8477 | 4747 | 52.75 | 1846.10 | 923.05 | 615.37 | 461.53 | 369.22 | 307.68 |
| 2001 | 7458 | 3878 | 43.09 | 1508.17 | 754.09 | 502.72 | 377.04 | 301.63 | 251.36 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
95' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14185 | 11348 | 119.45 | 4180.84 | 2090.42 | 1393.61 | 1045.21 | 836.17 | 696.81 |
| 2007 | 12966 | 9854 | 103.73 | 3630.48 | 1815.24 | 1210.16 | 907.62 | 726.10 | 605.08 |
| 2006 | 11526 | 8299 | 87.35 | 3057.42 | 1528.71 | 1019.14 | 764.36 | 611.48 | 509.57 |
| 2005 | 11286 | 7674 | 80.78 | 2827.44 | 1413.72 | 942.48 | 706.86 | 565.49 | 471.24 |
| 2004 | 8558 | 5477 | 57.65 | 2017.89 | 1008.94 | 672.63 | 504.47 | 403.58 | 336.31 |
| 2003 | 8828 | 5297 | 55.76 | 1951.45 | 975.73 | 650.48 | 487.86 | 390.29 | 325.24 |
| 2002 | 8828 | 4944 | 52.04 | 1821.36 | 910.68 | 607.12 | 455.34 | 364.27 | 303.56 |
| 2001 | 7810 | 4061 | 42.75 | 1496.23 | 748.12 | 498.74 | 374.06 | 299.25 | 249.37 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
100' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14324 | 11459 | 114.59 | 4010.72 | 2005.36 | 1336.91 | 1002.68 | 802.14 | 668.45 |
| 2007 | 13117 | 9969 | 99.69 | 3489.12 | 1744.56 | 1163.04 | 872.28 | 697.82 | 581.52 |
| 2006 | 12413 | 8937 | 89.37 | 3128.08 | 1564.04 | 1042.69 | 782.02 | 625.62 | 521.35 |
| 2005 | 12178 | 8281 | 82.81 | 2898.36 | 1449.18 | 966.12 | 724.59 | 579.67 | 483.06 |
| 2004 | 8558 | 5477 | 54.77 | 1916.99 | 958.50 | 639.00 | 479.25 | 383.40 | 319.50 |
| 2003 | 9201 | 5521 | 55.21 | 1932.21 | 966.11 | 644.07 | 483.05 | 386.44 | 322.04 |
| 2002 | 9201 | 5153 | 51.53 | 1803.40 | 901.70 | 601.13 | 450.85 | 360.68 | 300.57 |
| 2001 | 8183 | 4255 | 42.55 | 1489.31 | 744.65 | 496.44 | 372.33 | 297.86 | 248.22 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
105' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14639 | 11711 | 111.54 | 3903.73 | 1951.87 | 1301.24 | 975.93 | 780.75 | 650.62 |
| 2007 | 13398 | 10182 | 96.98 | 3394.16 | 1697.08 | 1131.39 | 848.54 | 678.83 | 565.69 |
| 2006 | 13001 | 9361 | 89.15 | 3120.24 | 1560.12 | 1040.08 | 780.06 | 624.05 | 520.04 |
| 2005 | 13005 | 8843 | 84.22 | 2947.80 | 1473.90 | 982.60 | 736.95 | 589.56 | 491.30 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2013 STRUCTURAL VALUES
WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
110' LIGHTWEIGHT STEEL POLES**

| Year Set | Actual Cost | 2013 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 16242 | 12994 | 118.12 | 4134.33 | 2067.16 | 1378.11 | 1033.58 | 826.87 | 689.05 |
| 2007 | 14773 | 11227 | 102.07 | 3572.38 | 1786.19 | 1190.79 | 893.10 | 714.48 | 595.40 |
| 2006 | 14479 | 10425 | 94.77 | 3317.01 | 1658.50 | 1105.67 | 829.25 | 663.40 | 552.83 |
| 2005 | 14256 | 9694 | 88.13 | 3084.48 | 1542.24 | 1028.16 | 771.12 | 616.90 | 514.08 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

