

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
30' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	3977	2983	99.43	2485.63	1242.81	828.54	621.41	497.13	414.27
2007	3468	2514	83.81	2095.25	1047.63	698.42	523.81	419.05	349.21
2006	3080	2156	71.87	1796.67	898.33	598.89	449.17	359.33	299.44
2005	2836	1914	63.81	1595.25	797.63	531.75	398.81	319.05	265.88
2004	2957	1922	64.07	1601.71	800.85	533.90	400.43	320.34	266.95
2003	2767	1729	57.65	1441.15	720.57	480.38	360.29	288.23	240.19
2002	2767	1660	55.34	1383.50	691.75	461.17	345.88	276.70	230.58
2001	2088	1201	40.02	1000.50	500.25	333.50	250.13	200.10	166.75
2000	2555	1405	46.84	1171.04	585.52	390.35	292.76	234.21	195.17
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 25 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
35' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4132	3099	88.54	2567.74	1283.87	855.91	641.94	513.55	427.96
2007	3591	2603	74.39	2157.17	1078.58	719.06	539.29	431.43	359.53
2006	3194	2236	63.88	1852.52	926.26	617.51	463.13	370.50	308.75
2005	2797	1888	53.94	1564.32	782.16	521.44	391.08	312.86	260.72
2004	2996	1947	55.64	1613.56	806.78	537.85	403.39	322.71	268.93
2003	2804	1753	50.07	1452.07	726.04	484.02	363.02	290.41	242.01
2002	2804	1682	48.07	1393.99	696.99	464.66	348.50	278.80	232.33
2001	2094	1204	34.40	997.64	498.82	332.55	249.41	199.53	166.27
2000	2583	1421	40.59	1177.11	588.56	392.37	294.28	235.42	196.19
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 29 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
40' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4728	3546	88.65	2659.50	1329.75	886.50	664.88	531.90	443.25
2007	4308	3123	78.08	2342.48	1171.24	780.83	585.62	468.50	390.41
2006	3836	2685	67.13	2013.90	1006.95	671.30	503.48	402.78	335.65
2005	3260	2201	55.01	1650.38	825.19	550.13	412.59	330.08	275.06
2004	3482	2263	56.58	1697.48	848.74	565.83	424.37	339.50	282.91
2003	3271	2044	51.11	1533.28	766.64	511.09	383.32	306.66	255.55
2002	3271	1963	49.07	1471.95	735.98	490.65	367.99	294.39	245.33
2001	2566	1475	36.89	1106.59	553.29	368.86	276.65	221.32	184.43
2000	3141	1728	43.19	1295.66	647.83	431.89	323.92	259.13	215.94
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
45' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5031	3773	83.85	2515.50	1257.75	838.50	628.88	503.10	419.25
2007	4587	3326	73.90	2217.05	1108.53	739.02	554.26	443.41	369.51
2006	4087	2861	63.58	1907.27	953.63	635.76	476.82	381.45	317.88
2005	3299	2227	49.49	1484.55	742.28	494.85	371.14	296.91	247.43
2004	3628	2358	52.40	1572.13	786.07	524.04	393.03	314.43	262.02
2003	3429	2143	47.63	1428.75	714.38	476.25	357.19	285.75	238.13
2002	3429	2057	45.72	1371.60	685.80	457.20	342.90	274.32	228.60
2001	2696	1550	34.45	1033.47	516.73	344.49	258.37	206.69	172.24
2000	3284	1806	40.14	1204.13	602.07	401.38	301.03	240.83	200.69
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
50' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5614	4211	84.21	2610.51	1305.26	870.17	652.63	522.10	435.09
2007	5125	3716	74.31	2303.69	1151.84	767.90	575.92	460.74	383.95
2006	4592	3214	64.29	1992.93	996.46	664.31	498.23	398.59	332.15
2005	3722	2512	50.25	1557.66	778.83	519.22	389.41	311.53	259.61
2004	3742	2432	48.65	1508.03	754.01	502.68	377.01	301.61	251.34
2003	4196	2623	52.45	1625.95	812.98	541.98	406.49	325.19	270.99
2002	4196	2518	50.35	1560.91	780.46	520.30	390.23	312.18	260.15
2001	3386	1947	38.94	1207.11	603.55	402.37	301.78	241.42	201.18
2000	4171	2294	45.88	1422.31	711.16	474.10	355.58	284.46	237.05
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
55' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	6586	4940	89.81	2784.08	1392.04	928.03	696.02	556.82	464.01
2007	6042	4380	79.64	2468.98	1234.49	822.99	617.25	493.80	411.50
2006	5180	3626	65.93	2043.75	1021.87	681.25	510.94	408.75	340.62
2005	4496	3035	55.18	1710.52	855.26	570.17	427.63	342.10	285.09
2004	4507	2930	53.26	1651.20	825.60	550.40	412.80	330.24	275.20
2003	5643	3527	64.13	1987.88	993.94	662.63	496.97	397.58	331.31
2002	5643	3386	61.56	1908.36	954.18	636.12	477.09	381.67	318.06
2001	4721	2715	49.36	1530.03	765.02	510.01	382.51	306.01	255.01
2000	5480	3014	54.80	1698.80	849.40	566.27	424.70	339.76	283.13
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
60' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	9333	7000	116.66	3733.20	1866.60	1244.40	933.30	746.64	622.20
2007	8639	6263	104.39	3340.41	1670.21	1113.47	835.10	668.08	556.74
2006	6211	4348	72.46	2318.77	1159.39	772.92	579.69	463.75	386.46
2005	5084	3432	57.20	1830.24	915.12	610.08	457.56	366.05	305.04
2004	5103	3317	55.28	1769.04	884.52	589.68	442.26	353.81	294.84
2003	6135	3834	63.91	2045.00	1022.50	681.67	511.25	409.00	340.83
2002	6135	3681	61.35	1963.20	981.60	654.40	490.80	392.64	327.20
2001	4924	2831	47.19	1510.03	755.01	503.34	377.51	302.01	251.67
2000	6141	3378	56.29	1801.36	900.68	600.45	450.34	360.27	300.23
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
65' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	10533	7900	121.53	3889.11	1944.55	1296.37	972.28	777.82	648.18
2007	10089	7315	112.53	3601.00	1800.50	1200.33	900.25	720.20	600.17
2006	9604	6723	103.43	3309.69	1654.84	1103.23	827.42	661.94	551.61
2005	6381	4307	66.26	2120.46	1060.23	706.82	530.11	424.09	353.41
2004	6410	4167	64.10	2051.20	1025.60	683.73	512.80	410.24	341.87
2003	6950	4344	66.83	2138.46	1069.23	712.82	534.62	427.69	356.41
2002	6950	4170	64.15	2052.92	1026.46	684.31	513.23	410.58	342.15
2001	5618	3230	49.70	1590.33	795.16	530.11	397.58	318.07	265.05
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
70' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	11167	8375	119.65	3948.33	1974.17	1316.11	987.08	789.67	658.06
2007	11047	8009	114.42	3775.71	1887.85	1258.57	943.93	755.14	629.28
2006	9604	6723	96.04	3169.32	1584.66	1056.44	792.33	633.86	528.22
2005	6574	4437	63.39	2091.94	1045.97	697.31	522.99	418.39	348.66
2004	6606	4294	61.34	2024.27	1012.13	674.76	506.07	404.85	337.38
2003	7368	4605	65.79	2170.93	1085.46	723.64	542.73	434.19	361.82
2002	7368	4421	63.15	2084.09	1042.05	694.70	521.02	416.82	347.35
2001	5945	3418	48.83	1611.52	805.76	537.17	402.88	322.30	268.59
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
30' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	1092	819	27.30	682.50	341.25	227.50	170.63	136.50	113.75
2007	942	683	22.77	569.13	284.56	189.71	142.28	113.83	94.85
2006	920	644	21.47	536.67	268.33	178.89	134.17	107.33	89.44
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 25 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
35' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	1212	909	25.97	753.17	376.59	251.06	188.29	150.63	125.53
2007	1039	753	21.52	624.14	312.07	208.05	156.04	124.83	104.02
2006	1018	713	20.36	590.44	295.22	196.81	147.61	118.09	98.41
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 29 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
40' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	1342	1007	25.16	754.88	377.44	251.63	188.72	150.98	125.81
2007	1306	947	23.67	710.14	355.07	236.71	177.53	142.03	118.36
2006	1281	897	22.42	672.53	336.26	224.18	168.13	134.51	112.09
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
45' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	1575	1181	26.25	787.50	393.75	262.50	196.88	157.50	131.25
2007	1523	1104	24.54	736.12	368.06	245.37	184.03	147.22	122.69
2006	1494	1046	23.24	697.20	348.60	232.40	174.30	139.44	116.20
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
50' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	2025	1519	30.38	941.63	470.81	313.88	235.41	188.33	156.94
2007	1953	1416	28.32	877.87	438.94	292.62	219.47	175.57	146.31
2006	1923	1346	26.92	834.58	417.29	278.19	208.65	166.92	139.10
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
55' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	2775	2081	37.84	1173.07	586.53	391.02	293.27	234.61	195.51
2007	2679	1942	35.31	1094.74	547.37	364.91	273.68	218.95	182.46
2006	2424	1697	30.85	956.38	478.19	318.79	239.09	191.28	159.40
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
60' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4893	3670	61.16	1957.20	978.60	652.40	489.30	391.44	326.20
2007	4734	3432	57.20	1830.48	915.24	610.16	457.62	366.10	305.08
2006	3301	2311	38.51	1232.37	616.19	410.79	308.09	246.47	205.40
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
65' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5490	4118	63.35	2027.08	1013.54	675.69	506.77	405.42	337.85
2007	5581	4046	62.25	1991.99	995.99	664.00	498.00	398.40	332.00
2006	5904	4133	63.58	2034.61	1017.30	678.20	508.65	406.92	339.10
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
70' COMPOSITE FIBERGLASS POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5495	4121	58.88	1942.88	971.44	647.63	485.72	388.58	323.81
2007	5581	4046	57.80	1907.51	953.75	635.84	476.88	381.50	317.92
2006	5904	4133	59.04	1948.32	974.16	649.44	487.08	389.66	324.72
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.