

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
55' DUCTILE IRON POLE**

City of Anaheim (D)

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	7147	6611	120.20	3726.19	1863.09	1242.06	931.55	745.24	621.03
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 31 feet of Common Area per Section 16 of the *Routine Handbook*.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
60' DUCTILE IRON POLE**

City of Anaheim (D)

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	7545	6979	116.32	3722.20	1861.10	1240.73	930.55	744.44	620.37
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
65' DUCTILE IRON POLE**

City of Anaheim (D)

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	7780	7197	110.72	3542.89	1771.45	1180.96	885.72	708.58	590.48
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
55' DUCTILE IRON POLE**

City of Anaheim (D)

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	2633	2436	44.28	1372.75	686.38	457.58	343.19	274.55	228.79
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 31 feet of Common Area per Section 16 of the *Routine Handbook*.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
60' DUCTILE IRON POLE**

City of Anaheim (D)

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	2633	2436	40.59	1298.95	649.47	432.98	324.74	259.79	216.49
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
65' DUCTILE IRON POLE**

City of Anaheim (D)

Year Set	Actual Cost	2019 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2019	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	2633	2436	37.47	1199.03	599.51	399.68	299.76	239.81	199.84
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.