

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
35' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2007 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2006 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 2416 | 1510 | 43.14 | 1251.14 | 625.57 | 417.05 | 312.79 | 250.23 | 208.52 |
| 2003 | 1927 | 1156 | 33.03 | 957.99 | 479.00 | 319.33 | 239.50 | 191.60 | 159.67 |
| 2002 | 1927 | 1108 | 31.66 | 918.08 | 459.04 | 306.03 | 229.52 | 183.62 | 153.01 |
| 2001 | 1448 | 796 | 22.75 | 659.87 | 329.94 | 219.96 | 164.97 | 131.97 | 109.98 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 29 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
40' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 7848 | 5690 | 142.25 | 4267.35 | 2133.68 | 1422.45 | 1066.84 | 853.47 | 711.23 |
| 2007 | 6885 | 4820 | 120.49 | 3614.63 | 1807.31 | 1204.88 | 903.66 | 722.93 | 602.44 |
| 2006 | 6494 | 4383 | 109.59 | 3287.59 | 1643.79 | 1095.86 | 821.90 | 657.52 | 547.93 |
| 2005 | 5967 | 3879 | 96.96 | 2908.91 | 1454.46 | 969.64 | 727.23 | 581.78 | 484.82 |
| 2004 | 3201 | 2001 | 50.02 | 1500.47 | 750.23 | 500.16 | 375.12 | 300.09 | 250.08 |
| 2003 | 2603 | 1562 | 39.05 | 1171.35 | 585.68 | 390.45 | 292.84 | 234.27 | 195.23 |
| 2002 | 2603 | 1497 | 37.42 | 1122.54 | 561.27 | 374.18 | 280.64 | 224.51 | 187.09 |
| 2001 | 1794 | 987 | 24.67 | 740.03 | 370.01 | 246.68 | 185.01 | 148.01 | 123.34 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
45' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8072 | 5852 | 130.05 | 3901.47 | 1950.73 | 1300.49 | 975.37 | 780.29 | 650.24 |
| 2007 | 7101 | 4971 | 110.46 | 3313.80 | 1656.90 | 1104.60 | 828.45 | 662.76 | 552.30 |
| 2006 | 6783 | 4579 | 101.75 | 3052.35 | 1526.18 | 1017.45 | 763.09 | 610.47 | 508.73 |
| 2005 | 6191 | 4024 | 89.43 | 2682.77 | 1341.38 | 894.26 | 670.69 | 536.55 | 447.13 |
| 2004 | 3314 | 2071 | 46.03 | 1380.83 | 690.42 | 460.28 | 345.21 | 276.17 | 230.14 |
| 2003 | 2703 | 1622 | 36.04 | 1081.20 | 540.60 | 360.40 | 270.30 | 216.24 | 180.20 |
| 2002 | 2703 | 1554 | 34.54 | 1036.15 | 518.08 | 345.38 | 259.04 | 207.23 | 172.69 |
| 2001 | 1834 | 1009 | 22.42 | 672.47 | 336.23 | 224.16 | 168.12 | 134.49 | 112.08 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
50' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 7547 | 5472 | 109.43 | 3392.38 | 1696.19 | 1130.79 | 848.09 | 678.48 | 565.40 |
| 2007 | 6622 | 4635 | 92.71 | 2873.95 | 1436.97 | 957.98 | 718.49 | 574.79 | 478.99 |
| 2006 | 6267 | 4230 | 84.60 | 2622.74 | 1311.37 | 874.25 | 655.68 | 524.55 | 437.12 |
| 2005 | 5677 | 3690 | 73.80 | 2287.83 | 1143.92 | 762.61 | 571.96 | 457.57 | 381.31 |
| 2004 | 3450 | 2156 | 43.13 | 1336.88 | 668.44 | 445.63 | 334.22 | 267.38 | 222.81 |
| 2003 | 4557 | 2734 | 54.68 | 1695.20 | 847.60 | 565.07 | 423.80 | 339.04 | 282.53 |
| 2002 | 4557 | 2620 | 52.41 | 1624.57 | 812.29 | 541.52 | 406.14 | 324.91 | 270.76 |
| 2001 | 3689 | 2029 | 40.58 | 1257.95 | 628.97 | 419.32 | 314.49 | 251.59 | 209.66 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
55' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8364 | 6064 | 110.25 | 3417.83 | 1708.92 | 1139.28 | 854.46 | 683.57 | 569.64 |
| 2007 | 7325 | 5128 | 93.23 | 2890.05 | 1445.02 | 963.35 | 722.51 | 578.01 | 481.67 |
| 2006 | 6879 | 4643 | 84.42 | 2617.15 | 1308.57 | 872.38 | 654.29 | 523.43 | 436.19 |
| 2005 | 6694 | 4351 | 79.11 | 2452.44 | 1226.22 | 817.48 | 613.11 | 490.49 | 408.74 |
| 2004 | 5869 | 3668 | 66.69 | 2067.49 | 1033.74 | 689.16 | 516.87 | 413.50 | 344.58 |
| 2003 | 5383 | 3230 | 58.72 | 1820.43 | 910.22 | 606.81 | 455.11 | 364.09 | 303.41 |
| 2002 | 5383 | 3095 | 56.28 | 1744.58 | 872.29 | 581.53 | 436.15 | 348.92 | 290.76 |
| 2001 | 4514 | 2483 | 45.14 | 1399.34 | 699.67 | 466.45 | 349.84 | 279.87 | 233.22 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
60' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 8856 | 6421 | 107.01 | 3424.32 | 1712.16 | 1141.44 | 856.08 | 684.86 | 570.72 |
| 2007 | 7772 | 5440 | 90.67 | 2901.55 | 1450.77 | 967.18 | 725.39 | 580.31 | 483.59 |
| 2006 | 7740 | 5225 | 87.08 | 2786.40 | 1393.20 | 928.80 | 696.60 | 557.28 | 464.40 |
| 2005 | 7559 | 4913 | 81.89 | 2620.45 | 1310.23 | 873.48 | 655.11 | 524.09 | 436.74 |
| 2004 | 5943 | 3714 | 61.91 | 1981.00 | 990.50 | 660.33 | 495.25 | 396.20 | 330.17 |
| 2003 | 5977 | 3586 | 59.77 | 1912.64 | 956.32 | 637.55 | 478.16 | 382.53 | 318.77 |
| 2002 | 5977 | 3437 | 57.28 | 1832.95 | 916.47 | 610.98 | 458.24 | 366.59 | 305.49 |
| 2001 | 5048 | 2776 | 46.27 | 1480.75 | 740.37 | 493.58 | 370.19 | 296.15 | 246.79 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
65' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 9824 | 7122 | 109.58 | 3506.41 | 1753.21 | 1168.80 | 876.60 | 701.28 | 584.40 |
| 2007 | 8630 | 6041 | 92.94 | 2974.03 | 1487.02 | 991.34 | 743.51 | 594.81 | 495.67 |
| 2006 | 8376 | 5654 | 86.98 | 2783.41 | 1391.70 | 927.80 | 695.85 | 556.68 | 463.90 |
| 2005 | 8166 | 5308 | 81.66 | 2613.12 | 1306.56 | 871.04 | 653.28 | 522.62 | 435.52 |
| 2004 | 6432 | 4020 | 61.85 | 1979.08 | 989.54 | 659.69 | 494.77 | 395.82 | 329.85 |
| 2003 | 6448 | 3869 | 59.52 | 1904.64 | 952.32 | 634.88 | 476.16 | 380.93 | 317.44 |
| 2002 | 6448 | 3708 | 57.04 | 1825.28 | 912.64 | 608.43 | 456.32 | 365.06 | 304.21 |
| 2001 | 5520 | 3036 | 46.71 | 1494.65 | 747.32 | 498.22 | 373.66 | 298.93 | 249.11 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
70' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 10809 | 7837 | 111.95 | 3694.36 | 1847.18 | 1231.45 | 923.59 | 738.87 | 615.73 |
| 2007 | 9931 | 6952 | 99.31 | 3277.23 | 1638.62 | 1092.41 | 819.31 | 655.45 | 546.21 |
| 2006 | 8911 | 6015 | 85.93 | 2835.61 | 1417.80 | 945.20 | 708.90 | 567.12 | 472.60 |
| 2005 | 8704 | 5658 | 80.82 | 2667.15 | 1333.58 | 889.05 | 666.79 | 533.43 | 444.53 |
| 2004 | 6771 | 4232 | 60.46 | 1995.03 | 997.51 | 665.01 | 498.76 | 399.01 | 332.50 |
| 2003 | 6833 | 4100 | 58.57 | 1932.76 | 966.38 | 644.25 | 483.19 | 386.55 | 322.13 |
| 2002 | 6833 | 3929 | 56.13 | 1852.23 | 926.12 | 617.41 | 463.06 | 370.45 | 308.71 |
| 2001 | 5904 | 3247 | 46.39 | 1530.82 | 765.41 | 510.27 | 382.71 | 306.16 | 255.14 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
75' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 11590 | 8403 | 112.04 | 3697.21 | 1848.61 | 1232.40 | 924.30 | 739.44 | 616.20 |
| 2007 | 10600 | 7420 | 98.93 | 3264.80 | 1632.40 | 1088.27 | 816.20 | 652.96 | 544.13 |
| 2006 | 9512 | 6421 | 85.61 | 2825.06 | 1412.53 | 941.69 | 706.27 | 565.01 | 470.84 |
| 2005 | 9308 | 6050 | 80.67 | 2662.09 | 1331.04 | 887.36 | 665.52 | 532.42 | 443.68 |
| 2004 | 7153 | 4471 | 59.61 | 1967.08 | 983.54 | 655.69 | 491.77 | 393.42 | 327.85 |
| 2003 | 7171 | 4303 | 57.37 | 1893.14 | 946.57 | 631.05 | 473.29 | 378.63 | 315.52 |
| 2002 | 7171 | 4123 | 54.98 | 1814.26 | 907.13 | 604.75 | 453.57 | 362.85 | 302.38 |
| 2001 | 6242 | 3433 | 45.77 | 1510.56 | 755.28 | 503.52 | 377.64 | 302.11 | 251.76 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
80' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 11933 | 8651 | 108.14 | 3676.86 | 1838.43 | 1225.62 | 919.21 | 735.37 | 612.81 |
| 2007 | 10913 | 7639 | 95.49 | 3246.62 | 1623.31 | 1082.21 | 811.65 | 649.32 | 541.10 |
| 2006 | 9885 | 6672 | 83.40 | 2835.76 | 1417.88 | 945.25 | 708.94 | 567.15 | 472.63 |
| 2005 | 9680 | 6292 | 78.65 | 2674.10 | 1337.05 | 891.37 | 668.53 | 534.82 | 445.68 |
| 2004 | 7383 | 4614 | 57.68 | 1961.11 | 980.55 | 653.70 | 490.28 | 392.22 | 326.85 |
| 2003 | 7664 | 4598 | 57.48 | 1954.32 | 977.16 | 651.44 | 488.58 | 390.86 | 325.72 |
| 2002 | 7664 | 4407 | 55.09 | 1872.89 | 936.45 | 624.30 | 468.22 | 374.58 | 312.15 |
| 2001 | 6735 | 3704 | 46.30 | 1574.31 | 787.15 | 524.77 | 393.58 | 314.86 | 262.38 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
85' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 12505 | 9066 | 106.66 | 3626.45 | 1813.23 | 1208.82 | 906.61 | 725.29 | 604.41 |
| 2007 | 11416 | 7991 | 94.01 | 3196.48 | 1598.24 | 1065.49 | 799.12 | 639.30 | 532.75 |
| 2006 | 10501 | 7088 | 83.39 | 2835.27 | 1417.64 | 945.09 | 708.82 | 567.05 | 472.55 |
| 2005 | 10300 | 6695 | 78.76 | 2678.00 | 1339.00 | 892.67 | 669.50 | 535.60 | 446.33 |
| 2004 | 7643 | 4777 | 56.20 | 1910.75 | 955.38 | 636.92 | 477.69 | 382.15 | 318.46 |
| 2003 | 7627 | 4576 | 53.84 | 1830.48 | 915.24 | 610.16 | 457.62 | 366.10 | 305.08 |
| 2002 | 7627 | 4386 | 51.59 | 1754.21 | 877.11 | 584.74 | 438.55 | 350.84 | 292.37 |
| 2001 | 6698 | 3684 | 43.34 | 1473.56 | 736.78 | 491.19 | 368.39 | 294.71 | 245.59 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
90' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 13797 | 10003 | 111.14 | 3889.99 | 1944.99 | 1296.66 | 972.50 | 778.00 | 648.33 |
| 2007 | 12616 | 8831 | 98.12 | 3434.36 | 1717.18 | 1144.79 | 858.59 | 686.87 | 572.39 |
| 2006 | 10848 | 7322 | 81.36 | 2847.60 | 1423.80 | 949.20 | 711.90 | 569.52 | 474.60 |
| 2005 | 10604 | 6893 | 76.58 | 2680.46 | 1340.23 | 893.49 | 670.11 | 536.09 | 446.74 |
| 2004 | 8259 | 5162 | 57.35 | 2007.40 | 1003.70 | 669.13 | 501.85 | 401.48 | 334.57 |
| 2003 | 8477 | 5086 | 56.51 | 1977.97 | 988.98 | 659.32 | 494.49 | 395.59 | 329.66 |
| 2002 | 8477 | 4874 | 54.16 | 1895.55 | 947.78 | 631.85 | 473.89 | 379.11 | 315.93 |
| 2001 | 7458 | 4102 | 45.58 | 1595.18 | 797.59 | 531.73 | 398.80 | 319.04 | 265.86 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
95' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14185 | 10284 | 108.25 | 3788.89 | 1894.44 | 1262.96 | 947.22 | 757.78 | 631.48 |
| 2007 | 12966 | 9076 | 95.54 | 3343.86 | 1671.93 | 1114.62 | 835.97 | 668.77 | 557.31 |
| 2006 | 11526 | 7780 | 81.90 | 2866.33 | 1433.17 | 955.44 | 716.58 | 573.27 | 477.72 |
| 2005 | 11286 | 7336 | 77.22 | 2702.70 | 1351.35 | 900.90 | 675.68 | 540.54 | 450.45 |
| 2004 | 8558 | 5349 | 56.30 | 1970.59 | 985.30 | 656.86 | 492.65 | 394.12 | 328.43 |
| 2003 | 8828 | 5297 | 55.76 | 1951.45 | 975.73 | 650.48 | 487.86 | 390.29 | 325.24 |
| 2002 | 8828 | 5076 | 53.43 | 1870.14 | 935.07 | 623.38 | 467.54 | 374.03 | 311.69 |
| 2001 | 7810 | 4296 | 45.22 | 1582.55 | 791.28 | 527.52 | 395.64 | 316.51 | 263.76 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
100' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14324 | 10385 | 103.85 | 3634.72 | 1817.36 | 1211.57 | 908.68 | 726.94 | 605.79 |
| 2007 | 13117 | 9182 | 91.82 | 3213.67 | 1606.83 | 1071.22 | 803.42 | 642.73 | 535.61 |
| 2006 | 12413 | 8379 | 83.79 | 2932.57 | 1466.29 | 977.52 | 733.14 | 586.51 | 488.76 |
| 2005 | 12178 | 7916 | 79.16 | 2770.50 | 1385.25 | 923.50 | 692.62 | 554.10 | 461.75 |
| 2004 | 8558 | 5349 | 53.49 | 1872.06 | 936.03 | 624.02 | 468.02 | 374.41 | 312.01 |
| 2003 | 9201 | 5521 | 55.21 | 1932.21 | 966.11 | 644.07 | 483.05 | 386.44 | 322.04 |
| 2002 | 9201 | 5291 | 52.91 | 1851.70 | 925.85 | 617.23 | 462.93 | 370.34 | 308.62 |
| 2001 | 8183 | 4501 | 45.01 | 1575.23 | 787.61 | 525.08 | 393.81 | 315.05 | 262.54 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
105' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 14639 | 10613 | 101.08 | 3537.76 | 1768.88 | 1179.25 | 884.44 | 707.55 | 589.63 |
| 2007 | 13398 | 9379 | 89.32 | 3126.20 | 1563.10 | 1042.07 | 781.55 | 625.24 | 521.03 |
| 2006 | 13001 | 8776 | 83.58 | 2925.23 | 1462.61 | 975.08 | 731.31 | 585.05 | 487.54 |
| 2005 | 13005 | 8453 | 80.51 | 2817.75 | 1408.88 | 939.25 | 704.44 | 563.55 | 469.63 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 STRUCTURAL VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
110' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 16242 | 11775 | 107.05 | 3746.73 | 1873.37 | 1248.91 | 936.68 | 749.35 | 624.46 |
| 2007 | 14773 | 10341 | 94.01 | 3290.35 | 1645.18 | 1096.78 | 822.59 | 658.07 | 548.39 |
| 2006 | 14479 | 9773 | 88.85 | 3109.69 | 1554.85 | 1036.56 | 777.42 | 621.94 | 518.28 |
| 2005 | 14256 | 9266 | 84.24 | 2948.40 | 1474.20 | 982.80 | 737.10 | 589.68 | 491.40 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
35' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2007 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2006 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 29 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
40' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 3370 | 2443 | 61.08 | 1832.44 | 916.22 | 610.81 | 458.11 | 366.49 | 305.41 |
| 2007 | 3021 | 2115 | 52.87 | 1586.03 | 793.01 | 528.68 | 396.51 | 317.21 | 264.34 |
| 2006 | 3248 | 2192 | 54.81 | 1644.30 | 822.15 | 548.10 | 411.08 | 328.86 | 274.05 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
45' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 3543 | 2569 | 57.08 | 1712.45 | 856.23 | 570.82 | 428.11 | 342.49 | 285.41 |
| 2007 | 3192 | 2234 | 49.65 | 1489.60 | 744.80 | 496.53 | 372.40 | 297.92 | 248.27 |
| 2006 | 3440 | 2322 | 51.60 | 1548.00 | 774.00 | 516.00 | 387.00 | 309.60 | 258.00 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
50' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 2997 | 2173 | 43.46 | 1347.15 | 673.58 | 449.05 | 336.79 | 269.43 | 224.53 |
| 2007 | 2696 | 1887 | 37.74 | 1170.06 | 585.03 | 390.02 | 292.52 | 234.01 | 195.01 |
| 2006 | 3001 | 2026 | 40.51 | 1255.92 | 627.96 | 418.64 | 313.98 | 251.18 | 209.32 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
55' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 3478 | 2522 | 45.85 | 1421.24 | 710.62 | 473.75 | 355.31 | 284.25 | 236.87 |
| 2007 | 3116 | 2181 | 39.66 | 1229.40 | 614.70 | 409.80 | 307.35 | 245.88 | 204.90 |
| 2006 | 3393 | 2290 | 41.64 | 1290.88 | 645.44 | 430.29 | 322.72 | 258.18 | 215.15 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
60' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 3857 | 2796 | 46.61 | 1491.37 | 745.69 | 497.12 | 372.84 | 298.27 | 248.56 |
| 2007 | 3469 | 2428 | 40.47 | 1295.09 | 647.55 | 431.70 | 323.77 | 259.02 | 215.85 |
| 2006 | 4072 | 2749 | 45.81 | 1465.92 | 732.96 | 488.64 | 366.48 | 293.18 | 244.32 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
65' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 4090 | 2965 | 45.62 | 1459.82 | 729.91 | 486.61 | 364.95 | 291.96 | 243.30 |
| 2007 | 3685 | 2580 | 39.68 | 1269.91 | 634.95 | 423.30 | 317.48 | 253.98 | 211.65 |
| 2006 | 4329 | 2922 | 44.96 | 1438.56 | 719.28 | 479.52 | 359.64 | 287.71 | 239.76 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
70' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 4339 | 3146 | 44.94 | 1483.01 | 741.50 | 494.34 | 370.75 | 296.60 | 247.17 |
| 2007 | 3914 | 2740 | 39.14 | 1291.62 | 645.81 | 430.54 | 322.91 | 258.32 | 215.27 |
| 2006 | 4785 | 3230 | 46.14 | 1522.66 | 761.33 | 507.55 | 380.66 | 304.53 | 253.78 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
75' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 4835 | 3505 | 46.74 | 1542.37 | 771.18 | 514.12 | 385.59 | 308.47 | 257.06 |
| 2007 | 4353 | 3047 | 40.63 | 1340.72 | 670.36 | 446.91 | 335.18 | 268.14 | 223.45 |
| 2006 | 5297 | 3575 | 47.67 | 1573.21 | 786.60 | 524.40 | 393.30 | 314.64 | 262.20 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
80' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 5100 | 3698 | 46.22 | 1571.44 | 785.72 | 523.81 | 392.86 | 314.29 | 261.91 |
| 2007 | 4600 | 3220 | 40.25 | 1368.50 | 684.25 | 456.17 | 342.13 | 273.70 | 228.08 |
| 2006 | 5613 | 3789 | 47.36 | 1610.23 | 805.11 | 536.74 | 402.56 | 322.05 | 268.37 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
85' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 5374 | 3896 | 45.84 | 1558.46 | 779.23 | 519.49 | 389.62 | 311.69 | 259.74 |
| 2007 | 4855 | 3399 | 39.98 | 1359.40 | 679.70 | 453.13 | 339.85 | 271.88 | 226.57 |
| 2006 | 6138 | 4143 | 48.74 | 1657.26 | 828.63 | 552.42 | 414.32 | 331.45 | 276.21 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
90' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 5628 | 4080 | 45.34 | 1586.78 | 793.39 | 528.93 | 396.70 | 317.36 | 264.46 |
| 2007 | 5094 | 3566 | 39.62 | 1386.70 | 693.35 | 462.23 | 346.68 | 277.34 | 231.12 |
| 2006 | 5979 | 4036 | 44.84 | 1569.49 | 784.74 | 523.16 | 392.37 | 313.90 | 261.58 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
95' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|-----------------|--------------------|------------------|----------------------|---------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 5927 | 4297 | 45.23 | 1583.13 | 791.57 | 527.71 | 395.78 | 316.63 | 263.86 |
| 2007 | 5370 | 3759 | 39.57 | 1384.89 | 692.45 | 461.63 | 346.22 | 276.98 | 230.82 |
| 2006 | 6556 | 4425 | 46.58 | 1630.37 | 815.19 | 543.46 | 407.59 | 326.07 | 271.73 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
100' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 6035 | 4375 | 43.75 | 1531.38 | 765.69 | 510.46 | 382.85 | 306.28 | 255.23 |
| 2007 | 5490 | 3843 | 38.43 | 1345.05 | 672.53 | 448.35 | 336.26 | 269.01 | 224.18 |
| 2006 | 7310 | 4934 | 49.34 | 1726.99 | 863.49 | 575.66 | 431.75 | 345.40 | 287.83 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
105' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 6278 | 4552 | 43.35 | 1517.18 | 758.59 | 505.73 | 379.30 | 303.44 | 252.86 |
| 2007 | 5712 | 3998 | 38.08 | 1332.80 | 666.40 | 444.27 | 333.20 | 266.56 | 222.13 |
| 2006 | 7811 | 5272 | 50.21 | 1757.48 | 878.74 | 585.83 | 439.37 | 351.50 | 292.91 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2019 SALVAGE VALUES WITH DEPRECIATION COSTS,
PER FOOT COSTS & SHARED COSTS
110' LIGHTWEIGHT STEEL POLE**

| Year Set | Actual Cost | 2019 Cost | Per Foot Cost | Shared Cost* | 2 Owners Shared \$ | 3 Owners Shared \$ | 4 Owners Shared \$ | 5 Owners Shared \$ | 6 Owners Shared \$ |
|----------|-------------|-----------|---------------|--------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 2019 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2018 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2017 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2016 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2015 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2014 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2013 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2012 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2011 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2010 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2009 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2008 | 7514 | 5448 | 49.52 | 1733.34 | 866.67 | 577.78 | 433.34 | 346.67 | 288.89 |
| 2007 | 6801 | 4761 | 43.28 | 1514.77 | 757.38 | 504.92 | 378.69 | 302.95 | 252.46 |
| 2006 | 9068 | 6121 | 55.64 | 1947.56 | 973.78 | 649.19 | 486.89 | 389.51 | 324.59 |
| 2005 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2004 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2003 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2002 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2001 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 2000 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1999 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1998 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1997 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1996 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| 1995 | 0 | 0 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.