

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
55' DUCTILE IRON POLE**

**City of Anaheim (D)**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	7147	6790	123.45	3826.89	1913.45	1275.63	956.72	765.38	637.82
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the *Routine Handbook*.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
60' DUCTILE IRON POLE**

**City of Anaheim (D)**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	7545	7168	119.46	3822.80	1911.40	1274.27	955.70	764.56	637.13
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
65' DUCTILE IRON POLE**

**City of Anaheim (D)**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	7780	7391	113.71	3638.65	1819.32	1212.88	909.66	727.73	606.44
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
55' DUCTILE IRON POLE**

**City of Anaheim (D)**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	2633	2501	45.48	1409.85	704.93	469.95	352.46	281.97	234.98
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the *Routine Handbook*.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
60' DUCTILE IRON POLE**

**City of Anaheim (D)**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	2633	2501	41.69	1334.05	667.03	444.68	333.51	266.81	222.34
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
65' DUCTILE IRON POLE**

**City of Anaheim (D)**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	2633	2501	38.48	1231.43	615.72	410.48	307.86	246.29	205.24
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the *Routine Handbook*.