

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
35' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	2416	1570	44.87	1301.19	650.59	433.73	325.30	260.24	216.86
2003	1927	1204	34.41	997.91	498.96	332.64	249.48	199.58	166.32
2002	1927	1156	33.03	957.99	479.00	319.33	239.50	191.60	159.67
2001	1448	833	23.79	689.87	344.93	229.96	172.47	137.97	114.98
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 29 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
40' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	7848	5886	147.15	4414.50	2207.25	1471.50	1103.63	882.90	735.75
2007	6885	4992	124.79	3743.72	1871.86	1247.91	935.93	748.74	623.95
2006	6494	4546	113.65	3409.35	1704.68	1136.45	852.34	681.87	568.23
2005	5967	4028	100.69	3020.79	1510.40	1006.93	755.20	604.16	503.47
2004	3201	2081	52.02	1560.49	780.24	520.16	390.12	312.10	260.08
2003	2603	1627	40.67	1220.16	610.08	406.72	305.04	244.03	203.36
2002	2603	1562	39.05	1171.35	585.68	390.45	292.84	234.27	195.23
2001	1794	1032	25.79	773.66	386.83	257.89	193.42	154.73	128.94
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
45' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	8072	6054	134.53	4036.00	2018.00	1345.33	1009.00	807.20	672.67
2007	7101	5148	114.41	3432.15	1716.08	1144.05	858.04	686.43	572.03
2006	6783	4748	105.51	3165.40	1582.70	1055.13	791.35	633.08	527.57
2005	6191	4179	92.87	2785.95	1392.98	928.65	696.49	557.19	464.33
2004	3314	2154	47.87	1436.07	718.03	478.69	359.02	287.21	239.34
2003	2703	1689	37.54	1126.25	563.13	375.42	281.56	225.25	187.71
2002	2703	1622	36.04	1081.20	540.60	360.40	270.30	216.24	180.20
2001	1834	1055	23.43	703.03	351.52	234.34	175.76	140.61	117.17
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
50' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	7547	5660	113.21	3509.36	1754.68	1169.79	877.34	701.87	584.89
2007	6622	4801	96.02	2976.59	1488.29	992.20	744.15	595.32	496.10
2006	6267	4387	87.74	2719.88	1359.94	906.63	679.97	543.98	453.31
2005	5677	3832	76.64	2375.82	1187.91	791.94	593.96	475.16	395.97
2004	3450	2243	44.85	1390.35	695.18	463.45	347.59	278.07	231.73
2003	4557	2848	56.96	1765.84	882.92	588.61	441.46	353.17	294.31
2002	4557	2734	54.68	1695.20	847.60	565.07	423.80	339.04	282.53
2001	3689	2121	42.42	1315.13	657.56	438.38	328.78	263.03	219.19
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
55' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	8364	6273	114.05	3535.69	1767.85	1178.56	883.92	707.14	589.28
2007	7325	5311	96.56	2993.26	1496.63	997.75	748.32	598.65	498.88
2006	6879	4815	87.55	2714.08	1357.04	904.69	678.52	542.82	452.35
2005	6694	4518	82.15	2546.76	1273.38	848.92	636.69	509.35	424.46
2004	5869	3815	69.36	2150.19	1075.09	716.73	537.55	430.04	358.36
2003	5383	3364	61.17	1896.28	948.14	632.09	474.07	379.26	316.05
2002	5383	3230	58.72	1820.43	910.22	606.81	455.11	364.09	303.41
2001	4514	2596	47.19	1462.95	731.47	487.65	365.74	292.59	243.82
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
60' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	8856	6642	110.70	3542.40	1771.20	1180.80	885.60	708.48	590.40
2007	7772	5635	93.91	3005.17	1502.59	1001.72	751.29	601.03	500.86
2006	7740	5418	90.30	2889.60	1444.80	963.20	722.40	577.92	481.60
2005	7559	5102	85.04	2721.24	1360.62	907.08	680.31	544.25	453.54
2004	5943	3863	64.38	2060.24	1030.12	686.75	515.06	412.05	343.37
2003	5977	3736	62.26	1992.33	996.17	664.11	498.08	398.47	332.06
2002	5977	3586	59.77	1912.64	956.32	637.55	478.16	382.53	318.77
2001	5048	2903	48.38	1548.05	774.03	516.02	387.01	309.61	258.01
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
65' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	9824	7368	113.35	3627.32	1813.66	1209.11	906.83	725.46	604.55
2007	8630	6257	96.26	3080.25	1540.12	1026.75	770.06	616.05	513.37
2006	8376	5863	90.20	2886.50	1443.25	962.17	721.62	577.30	481.08
2005	8166	5512	84.80	2713.62	1356.81	904.54	678.41	542.72	452.27
2004	6432	4181	64.32	2058.24	1029.12	686.08	514.56	411.65	343.04
2003	6448	4030	62.00	1984.00	992.00	661.33	496.00	396.80	330.67
2002	6448	3869	59.52	1904.64	952.32	634.88	476.16	380.93	317.44
2001	5520	3174	48.83	1562.58	781.29	520.86	390.65	312.52	260.43
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
70' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	10809	8107	115.81	3821.75	1910.88	1273.92	955.44	764.35	636.96
2007	9931	7200	102.86	3394.27	1697.14	1131.42	848.57	678.85	565.71
2006	8911	6238	89.11	2940.63	1470.32	980.21	735.16	588.13	490.11
2005	8704	5875	83.93	2769.74	1384.87	923.25	692.43	553.95	461.62
2004	6771	4401	62.87	2074.83	1037.41	691.61	518.71	414.97	345.80
2003	6833	4271	61.01	2013.29	1006.65	671.10	503.32	402.66	335.55
2002	6833	4100	58.57	1932.76	966.38	644.25	483.19	386.55	322.13
2001	5904	3395	48.50	1600.41	800.20	533.47	400.10	320.08	266.73
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
75' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	11590	8693	115.90	3824.70	1912.35	1274.90	956.18	764.94	637.45
2007	10600	7685	102.47	3381.40	1690.70	1127.13	845.35	676.28	563.57
2006	9512	6658	88.78	2929.70	1464.85	976.57	732.42	585.94	488.28
2005	9308	6283	83.77	2764.48	1382.24	921.49	691.12	552.90	460.75
2004	7153	4649	61.99	2045.76	1022.88	681.92	511.44	409.15	340.96
2003	7171	4482	59.76	1972.03	986.01	657.34	493.01	394.41	328.67
2002	7171	4303	57.37	1893.14	946.57	631.05	473.29	378.63	315.52
2001	6242	3589	47.86	1579.23	789.61	526.41	394.81	315.85	263.20
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
80' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	11933	8950	111.87	3803.64	1901.82	1267.88	950.91	760.73	633.94
2007	10913	7912	98.90	3362.57	1681.28	1120.86	840.64	672.51	560.43
2006	9885	6920	86.49	2940.79	1470.39	980.26	735.20	588.16	490.13
2005	9680	6534	81.68	2776.95	1388.48	925.65	694.24	555.39	462.83
2004	7383	4799	59.99	2039.55	1019.78	679.85	509.89	407.91	339.93
2003	7664	4790	59.88	2035.75	1017.88	678.58	508.94	407.15	339.29
2002	7664	4598	57.48	1954.32	977.16	651.44	488.58	390.86	325.72
2001	6735	3873	48.41	1645.87	822.93	548.62	411.47	329.17	274.31
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
85' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	12505	9379	110.34	3751.50	1875.75	1250.50	937.88	750.30	625.25
2007	11416	8277	97.37	3310.64	1655.32	1103.55	827.66	662.13	551.77
2006	10501	7351	86.48	2940.28	1470.14	980.09	735.07	588.06	490.05
2005	10300	6953	81.79	2781.00	1390.50	927.00	695.25	556.20	463.50
2004	7643	4968	58.45	1987.18	993.59	662.39	496.80	397.44	331.20
2003	7627	4767	56.08	1906.75	953.38	635.58	476.69	381.35	317.79
2002	7627	4576	53.84	1830.48	915.24	610.16	457.62	366.10	305.08
2001	6698	3851	45.31	1540.54	770.27	513.51	385.14	308.11	256.76
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
90' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	13797	10348	114.98	4024.13	2012.06	1341.38	1006.03	804.83	670.69
2007	12616	9147	101.63	3557.01	1778.51	1185.67	889.25	711.40	592.84
2006	10848	7594	84.37	2953.07	1476.53	984.36	738.27	590.61	492.18
2005	10604	7158	79.53	2783.55	1391.78	927.85	695.89	556.71	463.93
2004	8259	5368	59.65	2087.69	1043.85	695.90	521.92	417.54	347.95
2003	8477	5298	58.87	2060.38	1030.19	686.79	515.10	412.08	343.40
2002	8477	5086	56.51	1977.97	988.98	659.32	494.49	395.59	329.66
2001	7458	4288	47.65	1667.69	833.85	555.90	416.92	333.54	277.95
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
95' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	14185	10639	111.99	3919.54	1959.77	1306.51	979.88	783.91	653.26
2007	12966	9400	98.95	3463.29	1731.64	1154.43	865.82	692.66	577.21
2006	11526	8068	84.93	2972.49	1486.25	990.83	743.12	594.50	495.42
2005	11286	7618	80.19	2806.65	1403.33	935.55	701.66	561.33	467.78
2004	8558	5563	58.55	2049.42	1024.71	683.14	512.35	409.88	341.57
2003	8828	5518	58.08	2032.76	1016.38	677.59	508.19	406.55	338.79
2002	8828	5297	55.76	1951.45	975.73	650.48	487.86	390.29	325.24
2001	7810	4491	47.27	1654.49	827.24	551.50	413.62	330.90	275.75
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
100' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	14324	10743	107.43	3760.05	1880.03	1253.35	940.01	752.01	626.68
2007	13117	9510	95.10	3328.44	1664.22	1109.48	832.11	665.69	554.74
2006	12413	8689	86.89	3041.19	1520.59	1013.73	760.30	608.24	506.86
2005	12178	8220	82.20	2877.05	1438.53	959.02	719.26	575.41	479.51
2004	8558	5563	55.63	1946.95	973.47	648.98	486.74	389.39	324.49
2003	9201	5751	57.51	2012.72	1006.36	670.91	503.18	402.54	335.45
2002	9201	5521	55.21	1932.21	966.11	644.07	483.05	386.44	322.04
2001	8183	4705	47.05	1646.83	823.41	548.94	411.71	329.37	274.47
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
105' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	14639	10979	104.56	3659.75	1829.88	1219.92	914.94	731.95	609.96
2007	13398	9714	92.51	3237.85	1618.93	1079.28	809.46	647.57	539.64
2006	13001	9101	86.67	3033.57	1516.78	1011.19	758.39	606.71	505.59
2005	13005	8778	83.60	2926.13	1463.06	975.38	731.53	585.23	487.69
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 STRUCTURAL VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
110' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	16242	12182	110.74	3875.93	1937.97	1291.98	968.98	775.19	645.99
2007	14773	10710	97.37	3407.86	1703.93	1135.95	851.97	681.57	567.98
2006	14479	10135	92.14	3224.87	1612.43	1074.96	806.22	644.97	537.48
2005	14256	9623	87.48	3061.80	1530.90	1020.60	765.45	612.36	510.30
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
35' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2007	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2006	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 29 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
40' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	3370	2528	63.19	1895.63	947.81	631.88	473.91	379.13	315.94
2007	3021	2190	54.76	1642.67	821.33	547.56	410.67	328.53	273.78
2006	3248	2274	56.84	1705.20	852.60	568.40	426.30	341.04	284.20
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
45' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	3543	2657	59.05	1771.50	885.75	590.50	442.88	354.30	295.25
2007	3192	2314	51.43	1542.80	771.40	514.27	385.70	308.56	257.13
2006	3440	2408	53.51	1605.33	802.67	535.11	401.33	321.07	267.56
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 30 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
50' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	2997	2248	44.96	1393.61	696.80	464.54	348.40	278.72	232.27
2007	2696	1955	39.09	1211.85	605.93	403.95	302.96	242.37	201.98
2006	3001	2101	42.01	1302.43	651.22	434.14	325.61	260.49	217.07
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
55' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	3478	2609	47.43	1470.25	735.12	490.08	367.56	294.05	245.04
2007	3116	2259	41.07	1273.31	636.66	424.44	318.33	254.66	212.22
2006	3393	2375	43.18	1338.69	669.35	446.23	334.67	267.74	223.12
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 31 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
60' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	3857	2893	48.21	1542.80	771.40	514.27	385.70	308.56	257.13
2007	3469	2515	41.92	1341.35	670.67	447.12	335.34	268.27	223.56
2006	4072	2850	47.51	1520.21	760.11	506.74	380.05	304.04	253.37
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
65' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4090	3068	47.19	1510.15	755.08	503.38	377.54	302.03	251.69
2007	3685	2672	41.10	1315.26	657.63	438.42	328.82	263.05	219.21
2006	4329	3030	46.62	1491.84	745.92	497.28	372.96	298.37	248.64
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 32 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
70' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4339	3254	46.49	1534.15	767.07	511.38	383.54	306.83	255.69
2007	3914	2838	40.54	1337.75	668.87	445.92	334.44	267.55	222.96
2006	4785	3350	47.85	1579.05	789.53	526.35	394.76	315.81	263.18
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
75' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	4835	3626	48.35	1595.55	797.78	531.85	398.89	319.11	265.93
2007	4353	3156	42.08	1388.61	694.30	462.87	347.15	277.72	231.43
2006	5297	3708	49.44	1631.48	815.74	543.83	407.87	326.30	271.91
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 33 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
80' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5100	3825	47.81	1625.63	812.81	541.88	406.41	325.13	270.94
2007	4600	3335	41.69	1417.38	708.69	472.46	354.34	283.48	236.23
2006	5613	3929	49.11	1669.87	834.93	556.62	417.47	333.97	278.31
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
85' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5374	4031	47.42	1612.20	806.10	537.40	403.05	322.44	268.70
2007	4855	3520	41.41	1407.95	703.98	469.32	351.99	281.59	234.66
2006	6138	4297	50.55	1718.64	859.32	572.88	429.66	343.73	286.44
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 34 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
90' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5628	4221	46.90	1641.50	820.75	547.17	410.38	328.30	273.58
2007	5094	3693	41.04	1436.23	718.11	478.74	359.06	287.25	239.37
2006	5979	4185	46.50	1627.62	813.81	542.54	406.90	325.52	271.27
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
95' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	5927	4445	46.79	1637.72	818.86	545.91	409.43	327.54	272.95
2007	5370	3893	40.98	1434.36	717.18	478.12	358.59	286.87	239.06
2006	6556	4589	48.31	1690.76	845.38	563.59	422.69	338.15	281.79
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
100' LIGHTWEIGHT STEEL POLE**

<b>Year Set</b>	<b>Actual Cost</b>	<b>2018 Cost</b>	<b>Per Foot Cost</b>	<b>Shared Cost*</b>	<b>2 Owners Shared \$</b>	<b>3 Owners Shared \$</b>	<b>4 Owners Shared \$</b>	<b>5 Owners Shared \$</b>	<b>6 Owners Shared \$</b>
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	6035	4526	45.26	1584.19	792.09	528.06	396.05	316.84	264.03
2007	5490	3980	39.80	1393.09	696.54	464.36	348.27	278.62	232.18
2006	7310	5117	51.17	1790.95	895.48	596.98	447.74	358.19	298.49
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
105' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	6278	4709	44.84	1569.50	784.75	523.17	392.38	313.90	261.58
2007	5712	4141	39.44	1380.40	690.20	460.13	345.10	276.08	230.07
2006	7811	5468	52.07	1822.57	911.28	607.52	455.64	364.51	303.76
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.

**2018 SALVAGE VALUES WITH DEPRECIATION COSTS,  
PER FOOT COSTS & SHARED COSTS  
110' LIGHTWEIGHT STEEL POLE**

Year Set	Actual Cost	2018 Cost	Per Foot Cost	Shared Cost*	2 Owners Shared \$	3 Owners Shared \$	4 Owners Shared \$	5 Owners Shared \$	6 Owners Shared \$
2018	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2017	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2016	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2015	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2014	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2013	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2012	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2011	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2010	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2009	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2008	7514	5636	51.23	1793.11	896.56	597.70	448.28	358.62	298.85
2007	6801	4931	44.82	1568.87	784.43	522.96	392.22	313.77	261.48
2006	9068	6348	57.71	2019.69	1009.85	673.23	504.92	403.94	336.62
2005	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2004	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2003	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2002	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2001	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
2000	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1999	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1998	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1997	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1996	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1995	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1994	0	0	0.00	0.00	0.00	0.00	0.00	0.00	0.00

\*Shared Costs are based on 35 feet of Common Area per Section 16 of the Routine Handbook.