

## **Southern California Joint Pole Committee**

279 E. Arrow Hwy., Suite 104  
San Dimas, CA 91773  
Phone (909) 599-3801  
Fax (909) 599-3825

**February 19, 2025**

A meeting of the **ad hoc Computer Communications Committee** took place on the above date, at 1:28 p.m. via teleconference. **Those in attendance were:**

Ms. Marisol Bailey	Southern California Edison
Ms. April DeBarge	Southern California Edison
Mr. Michael Pearson	Southern California Edison
Ms. Carla Stephen	Southern California Edison
Ms. Shelby Mulvehill	Southern California Edison
Mr. Cesar G. Rodriguez	Southern California Edison
Ms. Maria Ortiz	MCI/Metro ATS, XO Communications, MCI Telecommunications
Mr. John Bacon	City of Los Angeles
Mr. Lex Treepaisan	Frontier Communications
Ms. Megan LaMon	Crown Castle NG West Inc.
Mr. Jeremy Effinger	Crown Castle NG West Inc.
Ms. Aarize Dizon	Crown Castle NG West Inc.
Mr. Jeremy Harmon	Verizon Wireless
Mr. John Vu	City of Anaheim
Mr. Salvador Zambrano	City of Burbank
Mr. Nick Van Stryk	City of Vernon (Petrelli Electric)
Ms. Heidi Seropian	Extenet Systems
Ms. Linda McLean	Extenet Systems
Ms. Kay Black	AT&T California
Mr. Alvin Robielos	AT&T California
Ms. Joy Young	AT&T California
Mr. Robert Stanard	AT&T California
Mr. Julian Ruiz	AT&T California
Mr. Alex Parra	City of Riverside
Ms. Yesenia Delgado	Time-Warner Cable
Mr. Ben Coffey	City of Banning
Mr. Irvin Orzuna	City of Glendale
Ms. Lynne LaFrenais	Bear Valley Electric Services Inc.
Ms. Shawn Henderson	T-Mobile USA
Ms. Tamara Zaki	Boldyn Networks US LLC
Ms. Patti Ringo	Sonic Telecom, LLC
Ms. Angela Pranata	Committee Staff
Ms. Kathleen Allen	Committee Staff

Ms. Bailey called the meeting to order at 1:28 p.m.

### **Agenda Item 1 – Review of prior month’s minutes**

Ms. Bailey opened the meeting by asking if there were any questions or concerns regarding last month’s meeting minutes. No members commented or expressed concerns.

### **Agenda Item 2 - Miscellaneous items/New item numbers**

#### SCJPC Website Updates

Ms. Bailey provided an update on the SCJPC website, which has been operational since late November. She addressed a concern raised in the previous meeting regarding pole records and anchor information. Specifically, there was an issue where pole card information appeared to be cut off when viewed online.

Ms. LaFrenais acknowledged that she had been responsible for sending an example of the issue to Ms. Pranata but had not yet done so. She committed to sending it by the end of the day.

Additionally, Ms. Bailey raised a question about the functionality of the Advanced Pole Search and the wildcard (%) feature when searching for street names. Ms. McLean and Ms. Black mentioned that they had successfully used the wildcard in their searches. Ms. Ortiz stated that she was unable to use “W/O” (west of) in her search. Ms. Pranata requested that Ms. Ortiz email the issue so she could forward it to the web programmer for review.

Ms. Bailey asked Ms. Pranata to test a pole number search (656407E), but found that the issue appeared resolved during the meeting. She noted that if any problems persisted, members should send an email to Ms. Pranata for further investigation.

Ms. Bailey also asked Ms. Pranata to search for another pole, 2124417E, on the Quick Pole Search page, but no results were found. Ms. Pranata then conducted an internal database search and confirmed that the pole number did not exist in the database. She explained that missing records were typically caused by an SCJPC staff member mistakenly failing to enter the pole and advised members to report such cases via email for manual database updates.

#### Multiple Pole Search and Measurement Units

Ms. Ortiz raised a concern about the Multiple Pole Search feature, noting that location measurements in reports were displaying incorrectly. Instead of feet, some values appeared as inches. Ms. Pranata requested Ms. Ortiz to email a report with examples so that she could forward it to the web programmer for review.

## Pole Records Display

Ms. LaFrenais identified a specific pole number (5900BV) where information under "Additional Information" was being cut off. Ms. Pranata clarified that the formatting issue was due to how the data had been originally entered into the database rather than a technical issue with the website itself. If members encountered similar errors, they were advised to send specific examples to Ms. Pranata for correction.

## Browser Back Button Functionality

Several members, including Ms. Ortiz, reported that the back button on the browser did not return users to the last pole searched. Instead, when attempting to navigate back to previous pole records, users were redirected to an external search engine (e.g., Google) rather than their previous search results.

Ms. Pranata stated that she had previously escalated this issue, and the web programmer believed it had been resolved since she did not hear any feedback from members. To assist with troubleshooting, Ms. Pranata requested that members submit detailed steps, screenshots, or short video recordings to help the web programmer replicate and address the issue.

Ms. Ortiz agreed to send a short video demonstrating the problem.

## Other Miscellaneous Items

Ms. Bailey asked if there were any other miscellaneous items. There were no additional items.

## **Agenda Item 3 - Review of Action Items**

- Ms. Ortiz will email examples of incorrect measurement units in multiple pole search reports.
- Members encountering search and navigation issues on the SCJPC website should submit screenshots or videos to assist troubleshooting.

The meeting adjourned at 1:40 p.m. until March 19, 2025.

Transcribed by Angela Pranata - Committee Staff